



report date: 2024-03-29

General information

Make	VOLVO
Model	S80 D5 SE LUX AWD
Colour	Silver
Year of manufacture	2010
Top speed	130 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	205 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	40.9 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-03-29
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	16
Total items failed	12

MOT #15	2023-03-30 08:42
MOT test number	168501260607
Result	✓ Passed
Next expiry date	2024-03-29

MOT #14	2021-12-30 15:50
MOT test number	272673892523
Result	✓ Passed
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #13	2021-12-30 15:50
MOT test number	417359107522
Result	✗ Failed
Pass with rectification	Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Pass with rectification	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #12** 2020-12-17 09:41**MOT test number** 283359295514**Result** ✓ Passed**MOT #11** 2020-03-02 10:08**MOT test number** 283666229194**Result** ✓ Passed**MOT #10** 2020-03-02 10:08**MOT test number** 586466601952**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #9** 2019-03-04 10:26**MOT test number** 510843962899**Result** ✓ Passed**MOT #8** 2017-02-17 12:19**MOT test number** 866818591143**Result** ✓ Passed**Advice** Offside Front small nick in wiper blade**Advice** Offside Front Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**Advice** Rear n/s/r small cuts to tread// both tyres wearing to inner edges

**MOT #7** 2017-02-17 12:19**MOT test number** 548888842528**Result** ✗ Failed**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Front Headlamp aim too high (1.8)**Advice** Rear n/s/r small cuts to tread// both tyres wearing to inner edges**Advice** Offside Front Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Advice** Offside Front small knick in wiper blade**MOT #6** 2016-02-12 10:23**MOT test number** 299083687499**Result** ✓ Passed**MOT #5** 2015-02-17 13:10**MOT test number** 406438245026**Result** ✓ Passed**MOT #4** 2015-02-17 10:44**MOT test number** 148848145489**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #3** 2014-02-27 16:46**MOT test number** 598828754079**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2013-02-20 09:19**MOT test number** 406231153061**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-02-20 09:19**MOT test number** 625311953038**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✗
MOT
Expired:
29 March 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	29 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-01
Last registration	2023-03-30
Complete history	See info



Registration #1	2010-03-01	15 mi
Registration #2	2013-02-20	49.844 mi
Registration #3	2014-02-27	62.778 mi
Registration #4	2015-02-17	75.697 mi
Registration #5	2015-02-17	75.697 mi
Registration #6	2016-02-12	87.223 mi
Registration #7	2017-02-17	99.429 mi
Registration #8	2017-02-17	99.429 mi
Registration #9	2018-03-20	111.557 mi
Registration #10	2019-03-20	123.685 mi
Registration #11	2020-03-20	135.813 mi
Registration #12	2021-03-20	147.941 mi
Registration #13	2022-03-20	160.069 mi
Registration #14	2023-03-20	172.197 mi
Registration #15	2024-03-20	184.325 mi
Registration #16	2025-03-20	196.453 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1891 mm
Height	1713 mm
Length	4627 mm
Wheel base	2774 mm
Kerb weight	1867 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	868290