



report date: 2024-03-29

General information

Make	VOLVO
Model	XC60 D4 SE LUX NAV
Colour	Black
Year of manufacture	-
Top speed	130 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	178 BHP
Max. torque	400 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	60.1 mpg





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	<a href="#">View report</a>



source: autoonline.co.uk

**MOT history**

<b>MOT #5</b>	2021-02-25 14:20
<b>MOT test number</b>	711434965172
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-02-24

<b>MOT #4</b>	2021-02-24 16:07
<b>MOT test number</b>	250879104217
<b>Result</b>	✗ Failed

<b>Advice</b>	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Fail</b>	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
<b>Advice</b>	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Fail</b>	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Fail</b>	Nearside Front Service brake excessively fluctuating (1.2.1 (e))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Fail</b>	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
<b>Advice</b>	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Fail</b>	Offside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #3** 2020-10-01 12:32**MOT test number** 234008364730**Result** ✓ Passed

**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))

**Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt now sealed (2.1.3 (g) (i))

**Advice** Offside Front Fluid leak, but not excessive (8.4.1 (a) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

**MOT #2** 2019-01-09 12:12**MOT test number** 699310180793**Result** ✓ Passed**MOT #1** 2017-12-01 11:00**MOT test number** 808299539315**Result** ✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>PK64XUE</b>
Plate since	2019-09-29
Current registration	<b>PK64XUE</b>
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >





Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2014-12-15
Last registration	2021-02-25
Complete history	<a href="#">See info</a>



Registration #1	2014-12-15	6 mi
Registration #2	2017-12-01	31.891 mi
Registration #3	2019-01-09	43.327 mi
Registration #4	2020-10-01	55.061 mi
Registration #5	2021-02-25	55.061 mi
Registration #6	2021-02-25	55.061 mi
Registration #7	2021-02-25	55.061 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2120 mm
Height	1713 mm
Length	4644 mm
Wheel base	2774 mm
Kerb weight	1799 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1104691