




report date: 2024-03-29

General information

Make	VAUXHALL
Model	AGILA CLUB
Colour	Red
Year of manufacture	2009
Top speed	99 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	64 BHP
Max. torque	90 Nm at 4.800 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.9 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	120 g/km
CO2 label	C






Internet history

Entry 1

Date	2022-02-09
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-05-24
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	15
Total items failed	14

MOT #17	2023-05-25 10:24
MOT test number	322447936927
Result	✓ Passed
Next expiry date	2024-05-24

MOT #16	2023-05-25 10:24
MOT test number	438354374487
Result	✗ Failed
Pass with rectification	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
Pass with rectification	Offside Rear Service brake excessively binding (1.2.1 (f))

MOT #15	2022-04-22 10:09
MOT test number	352700680939
Result	✓ Passed

MOT #14	2021-05-10 10:06
MOT test number	172104191026
Result	✓ Passed

**MOT #13** 2021-05-10 08:19**MOT test number** 128419623271**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Windscreen washer not working (3.5 (a))**MOT #12** 2020-05-20 14:33**MOT test number** 626774720696**Result** ✓ Passed**MOT #11** 2020-05-20 11:06**MOT test number** 190865913718**Result** ✗ Failed**Fail** Offside Brake pipe excessively corroded Front to rear (1.1.11 (c))**Fail** Nearside Brake pipe excessively corroded Front to rear (1.1.11 (c))**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**MOT #10** 2019-04-08 13:19**MOT test number** 773490268183**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #9** 2019-04-08 09:57**MOT test number** 564383027125**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**MOT #8** 2018-04-04 11:18**MOT test number** 915007901640**Result** ✓ Passed**Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #7** 2017-04-13 07:25**MOT test number** 268065387546**Result** ✓ Passed**Advice** Body has slight corrosion (6.1.B.2)**MOT #6** 2017-04-05 10:23**MOT test number** 457884451646**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Body has slight corrosion (6.1.B.2)**Fail** Nearside Front coil spring broken (2.4.C.1a)**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

**MOT #5** 2016-04-09 09:57**MOT test number** 671644963987**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #4** 2015-04-16 09:08**MOT test number** 699236605156**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #3** 2014-04-26 09:54**MOT test number** 639706314139**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2013-04-25 08:53**MOT test number** 278595513166**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2012-04-28 13:21**MOT test number** 209989512164**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 March 2025

✓
MOT

Expires:
24 May 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	24 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2023-03-29
Current registration	 XXXXXX
Plate since	2023-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-04-30
Last registration	2023-05-25
Complete history	See info



Registration #1	2009-04-30	6 mi
Registration #2	2012-04-28	61.649 mi
Registration #3	2013-04-25	78.218 mi
Registration #4	2014-04-26	96.369 mi
Registration #5	2015-04-16	111.952 mi
Registration #6	2016-04-09	128.218 mi
Registration #7	2017-04-05	138.895 mi
Registration #8	2017-04-13	138.899 mi
Registration #9	2018-04-04	142.606 mi
Registration #10	2019-04-08	147.111 mi
Registration #11	2019-05-20	151.377 mi
Registration #12	2019-05-20	151.377 mi
Registration #13	2019-05-20	151.377 mi
Registration #14	2019-05-20	151.377 mi
Registration #15	2019-05-20	151.377 mi
Registration #16	2019-05-20	151.377 mi
Registration #17	2019-05-20	151.377 mi
Registration #18	2019-05-20	151.377 mi
Registration #19	2019-05-20	151.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	975 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	1034968