




report date: 2024-03-29

General information

Make	FORD
Model	S-MAX ZETEC TDCI
Colour	Green
Year of manufacture	2007
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	190 Nm at 4.500 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-12
Pictures	33
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-13
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	25
Total items failed	12

MOT #19 2023-05-24 08:01

MOT test number 931605889278

Result ✓ Passed

Next expiry date 2024-06-13

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18 2023-05-16 08:35

MOT test number 714476957880

Result ✗ Failed

- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Front Lower Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))



MOT #17	2022-06-06 12:36
MOT test number	474005486916
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Nearside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #16	2021-06-14 08:26
MOT test number	558408142038
Result	✓ Passed

MOT #15	2020-09-18 09:13
MOT test number	327824371272
Result	✓ Passed

MOT #14	2019-09-12 12:29
MOT test number	242387485797
Result	✓ Passed

MOT #13	2019-09-11 16:07
MOT test number	522872780591
Result	✗ Failed
Fail	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))



MOT #12 2018-09-14 09:27

MOT test number 386011041044

Result ✓ Passed

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11 2017-09-15 16:01

MOT test number 366766948500

Result ✓ Passed

- Advice** Child Seat fitted not allowing full inspection of adult belt 2 seats fitted

MOT #10 2017-09-15 16:01

MOT test number 452493769618

Result ✗ Failed

- Advice** Child Seat fitted not allowing full inspection of adult belt 2 seats fitted
- Pass with rectification** Nearside Headlamp aim too high (1.8)
- Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)

MOT #9 2016-09-16 13:00

MOT test number 964550989034

Result ✓ Passed

- Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Wipers slightly streaking



MOT #8 2015-09-12 09:33

MOT test number 345336108265

Result ✓ Passed

- Advice** CHILD SEATS FITTED
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #7 2014-09-12 10:57

MOT test number 616895654259

Result ✓ Passed

- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2014-09-12 10:57

MOT test number 947135254242

Result ✗ Failed

- Pass with rectification** Nearside Stop lamp not working (1.2.1b)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #5 2013-09-02 16:10

MOT test number 269215443268

Result ✓ Passed

MOT #4 2012-09-05 13:45

MOT test number 959929642250

Result ✓ Passed



MOT #3	2012-09-05 13:45
MOT test number	909089542211
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)
Pass with rectification	Offside Headlamp aim too low (1.8)

MOT #2	2011-09-06 10:43
MOT test number	997729141234
Result	✓ Passed

MOT #1	2010-09-08 12:22
MOT test number	941821450206
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
13 June 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	13 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-




Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 PK57FYC
Plate since	2024-03-29
Current registration	 PK57FYC
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-09-20
Last registration	2023-05-24
Complete history	See info



Registration #1	2007-09-20	8 mi
Registration #2	2010-09-08	42.720 mi
Registration #3	2011-09-06	56.831 mi
Registration #4	2012-09-05	62.363 mi
Registration #5	2013-09-02	67.151 mi
Registration #6	2014-09-12	73.178 mi
Registration #7	2015-09-12	80.775 mi
Registration #8	2016-09-16	86.899 mi
Registration #9	2017-09-15	92.904 mi
Registration #10	2017-09-15	92.904 mi
Registration #11	2018-05-24	95.277 mi
Registration #12	2018-05-24	95.277 mi
Registration #13	2018-05-24	95.277 mi
Registration #14	2018-05-24	95.277 mi
Registration #15	2018-05-24	95.277 mi
Registration #16	2018-05-24	95.277 mi
Registration #17	2018-05-24	95.277 mi
Registration #18	2018-05-24	95.277 mi
Registration #19	2018-05-24	95.277 mi

[More info >](#)



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1736 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

6R30967