



report date: 2024-03-29

General information

Make	VOLVO
Model	C70 D5 SE
Colour	White
Year of manufacture	2009
Top speed	140 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	180 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	28.0 mpg
Consumption extra urban	49.6 mpg
Consumption combined	38.7 mpg
CO2 emission	193 g/km
CO2 label	J





Internet history

Entry 3

Date 2023-12-14

Pictures 8



source: g3remarketing.co.uk

Entry 2

Date 2021-11-05

Pictures 49

Listing price [View report](#)



source: cargurus.co.uk

Entry 1

Date 2021-11-04

Pictures 0

Listing price [View report](#)

source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-21
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	11
Total items failed	5

MOT #18	2023-08-22 14:34
MOT test number	274514574678
Result	✓ Passed
Next expiry date	2024-08-21

MOT #17	2023-08-22 10:44
MOT test number	929226902074
Result	✗ Failed
MAJOR	Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
MAJOR	Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MOT #16	2022-11-14 09:09
MOT test number	589265481578
Result	✓ Passed

MOT #15	2021-11-05 10:56
MOT test number	343882715957
Result	✓ Passed

**MOT #14** 2021-03-03 17:00**MOT test number** 943647286829**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Valve stem slightly damaged (5.2.3 (j))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2020-03-03 12:01**MOT test number** 993800919736**Result** ✓ Passed**Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**MOT #12** 2020-03-03 12:01**MOT test number** 478603532141**Result** ✗ Failed**Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**MOT #11** 2019-03-06 16:57**MOT test number** 518834435865**Result** ✓ Passed**MOT #10** 2018-03-08 17:39**MOT test number** 210192390856**Result** ✓ Passed

**MOT #9** 2018-03-08 17:39**MOT test number** 387576831499**Result** ✗ Failed**Pass with rectification** Nearside Side repeater not working (1.4.A.2c)**MOT #8** 2017-03-08 15:22**MOT test number** 211354772020**Result** ✓ Passed**MOT #7** 2016-03-09 11:36**MOT test number** 894971385255**Result** ✓ Passed**MOT #6** 2015-03-18 11:29**MOT test number** 526257575075**Result** ✓ Passed**MOT #5** 2014-03-21 14:06**MOT test number** 177660984080**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #4** 2014-03-20 09:35**MOT test number** 978939874088**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #3** 2013-03-12 12:29**MOT test number** 808431873099**Result** ✓ Passed**MOT #2** 2013-03-12 12:29**MOT test number** 338651673044**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #1** 2012-03-22 10:55**MOT test number** 938592082039**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
21 August 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	21 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	AK09VEB
Plate since	2024-03-29
Current registration	AK09VEB
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-03-27
Last registration	2023-08-22
Complete history	See info



Registration #1	2009-03-27	19 mi
Registration #2	2012-03-22	20.572 mi
Registration #3	2013-03-12	26.617 mi
Registration #4	2014-03-20	33.110 mi
Registration #5	2014-03-21	33.110 mi
Registration #6	2015-03-18	40.104 mi
Registration #7	2016-03-09	46.773 mi
Registration #8	2017-03-08	53.818 mi
Registration #9	2018-03-08	63.549 mi
Registration #10	2018-03-08	63.549 mi
Registration #11	2019-03-08	63.549 mi
Registration #12	2019-03-08	63.549 mi
Registration #13	2019-03-08	63.549 mi
Registration #14	2019-03-08	63.549 mi
Registration #15	2019-03-08	63.549 mi
Registration #16	2019-03-08	63.549 mi
Registration #17	2019-03-08	63.549 mi
Registration #18	2019-03-08	63.549 mi
Registration #19	2019-03-08	63.549 mi
Registration #20	2019-03-08	63.549 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1987 mm
Height	1400 mm
Length	4582 mm
Wheel base	2640 mm
Kerb weight	1784 kg
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	672140