

Ford



General information

Make	FORD
Model	S-MAX ZETEC TDCI
Colour	Grey
Year of manufacture	2006
Top speed	116 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	285 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	164 g/km
CO2 label	G





MOT history

MOT expiry date	2021-11-29
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	25
Total items failed	0

MOT #13		2020-11-30 16:14
MOT test r	number	179580515841
Result		✓ Passed
Next expir	ry date	2021-11-29
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Inner Steering linkage ball joint has slight play rackend (2.1.3 (b) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2019-11-22 16:09
MOT test number	733299709566
Result	✓ Passed
MOT #11	2018-11-07 15:49
MOT test number	730588483499

Result

🗸 Passed



LT56EJA
report date: 2024-03-29

MOT #10	2018-11-07 13:30	
MOT test number	711543647231	
Result	🗙 Failed	
MAJOR Nearside Stop lamp(s) not working (4.3.1 (a) (ii))		
DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm edges	s worn (5.2.3 (e))	
MAJOR Offside Stop lamp(s) not working (4.3.1 (a) (ii))		
DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm edges worn (5.2.3 (e))		
МОТ #9	2017-11-23 15:16	
MOT test number	122055392601	
Result	✓ Passed	

Advice Nearside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #8	2016-11-12 11:17
MOT test number	865738652053
Result	✓ Passed
Advice Nearside Front Anti-roll bar linkage ball joint dust cover deteriorated, dirt (2.4.G.2)	but preventing the ingress of

MOT #7	2015-10-29 16:31
MOT test number	456774411384
Result	✓ Passed
MOT #6	2014-10-29 15:06

MOT test number	379272304359
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	





MOT #5		2013-10-07 10:54
MOT test	number	428120183258
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
MOT #4		2012-10-08 15:01
MOT test	number	196012682294
Result		✓ Passed
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #3	2011-10-05 11:14
MOT test number	167058771242
Result	✓ Passed

MOT #2	2010-09-23 17:18
MOT test number	691126560251
Result	✓ Passed



MOT #1		2009-09-21 13:26
MOT test	number	540854569266
Result		✓ Passed
Advice	Nearside Rear brake disc slightly pitted (3.5.1h)	
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.3	1i)
Advice	Offside Rear brake disc slightly pitted (3.5.1h)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5	5.1i)

LT56EJA

report date: 2024-03-29



Tax & MOT check

X Untaxed Tax expired: 16 January 2021	X MOT Expired: 29 November 2021
Tax status	Expired at 16 January 2021
Days left	1200 days too late
MOT expiry date	29 November 2021
Full MOT history	See MOT history
Tax calculation	
Vahiela elass	10

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2006-10-23
Last registration	2020-11-30
Complete history	See info



Registration #1	2006-10-23	23 mi
Registration #2	2009-09-21	811.772 mi
Registration #3	2010-09-23	96.009 mi
Registration #4	2011-10-05	107.709 mi
Registration #5	2012-10-08	120.264 mi
Registration #6	2013-10-07	136.222 mi
Registration #7	2014-10-29	146.040 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		
Registration #12		11.227 44
Registration #12 Registration #13		0.000 est

More info >





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
50566	
\$0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1736 kg
Max. allowed weight	2505 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12

Number of axles	2
Engine number	6J02982