



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK200K AVANTGARDE
Colour	Grey
Year of manufacture	2009
Top speed	144 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	181 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	31.7 mpg
CO2 emission	214 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-12-02
Pictures	9
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT expiry date	2024-09-07
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	47
Total items failed	3

MOT #14	2023-09-07 10:58
MOT test number	296324617758
Result	✓ Passed
Next expiry date	2024-09-07
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #13	2022-09-08 11:52
MOT test number	918192907402
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2020-11-13 15:51
MOT test number	725532138677
Result	✓ Passed
Advice	Front registration plate cracked



MOT #11

2019-11-14 13:09

MOT test number

165493480266

Result

✓ Passed

- Advice

Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice

Central Exhaust mounting defective (6.1.2 (a))
- Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Offside Rear Nail in tyre
- Advice

Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Nearside Front fog light craced
- Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice

Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice

Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice

Nearside Rear lens cracked

**MOT #10**

2019-11-13 14:56

MOT test number

834719035891

Result**✗ Failed**

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Nearside Front fog light craced
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Central Exhaust mounting defective (6.1.2 (a))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Rear lens cracked
- Advice** Offside Rear Nail in tyre
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #9

2018-11-16 14:33

MOT test number

704707229662

Result**✓ Passed**

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8** 2017-11-13 11:28**MOT test number** 492482706398**Result** ✓ Passed**MOT #7** 2016-11-16 11:50**MOT test number** 425234684754**Result** ✓ Passed**Advice** Advise near side rear tyre tread wearing low**Advice** Advise parking brake has only just met requirements , requires some adjustment**MOT #6** 2015-11-16 14:44**MOT test number** 905662674742**Result** ✓ Passed**MOT #5** 2014-11-17 12:17**MOT test number** 505311824331**Result** ✓ Passed**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Advise off side rear tyre,perishing and tread wearing low**Notice** Advise front and rear brake pads wearing low**MOT #4** 2013-11-17 13:05**MOT test number** 118001623372**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay



MOT #3	2013-09-02 14:44
MOT test number	738805243271
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #2	2013-09-02 11:12
MOT test number	128105543265
Result	✗ Failed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
Notice	Nearside front tyre perrished and cracked
Fail	Nearside Front Headlamp not working on dipped beam (1.7.5a)
Fail	Centre Rear Exhaust system not adequately supported (7.1.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1	2012-09-06 11:27
MOT test number	126340852225
Result	✓ Passed
Notice	Offside front tyre scrubbed on both edges



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
7 September 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	7 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	LN59OHG
Plate since	2019-09-29
Current registration	LN59OHG
Plate since	2019-09-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-09-10
Last registration	2023-09-07
Complete history	See info



Registration #1	2009-09-10	28 mi
Registration #2	2012-09-06	17.713 mi
Registration #3	2013-09-02	24.003 mi
Registration #4	2013-09-02	24.003 mi
Registration #5	2013-11-17	25.012 mi
Registration #6	2014-11-17	29.165 mi
Registration #7	2015-11-16	32.773 mi
Registration #8	2016-11-16	35.721 mi
Registration #9	2016-11-16	35.721 mi
Registration #10	2016-11-16	35.721 mi
Registration #11	2016-11-16	35.721 mi
Registration #12	2016-11-16	35.721 mi
Registration #13	2016-11-16	35.721 mi
Registration #14	2016-11-16	35.721 mi
Registration #15	2016-11-16	35.721 mi
Registration #16	2016-11-16	35.721 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1685 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27195531120793