



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 D3 SE LUX
Colour	White
Year of manufacture	2013
Top speed	127 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	350 Nm at 2.250 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2022-06-11
Pictures	19
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-22
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	9
Total items failed	12

MOT #13	2023-07-29 12:29
MOT test number	285582138015
Result	✓ Passed
Next expiry date	2024-08-22
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2022-08-23 13:24
MOT test number	534623072611
Result	✓ Passed

MOT #11	2022-08-22 08:07
MOT test number	748585265635
Result	✗ Failed
Advice	Rear Coil spring corroded x2 (5.3.1 (b) (i))
Advice	Rear Inner Brake disc worn, pitted or scored, but not seriously weakened x2 (1.1.14 (a) (ii))
Fail	Front Windscreen wiper does not clear the windscreen effectively x2 (3.4 (b) (ii))
Fail	Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Fail	Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #10** 2022-05-04 08:19**MOT test number** 472411277151**Result** ✓ Passed**MOT #9** 2022-05-04 08:19**MOT test number** 931372482966**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**MOT #8** 2021-01-07 14:42**MOT test number** 873675079141**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing inner outer edges worn (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing inner outer edge worn low (5.2.3 (d) (ii))**MOT #7** 2021-01-06 11:45**MOT test number** 986907336207**Result** ✗ Failed**Advice** Offside Front Tyre slightly damaged/cracking or perishing inner outer edges worn (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing inner outer edge worn low (5.2.3 (d) (ii))**Minor** Nearside Front Brake hose slightly twisted (1.1.12 (b) (i))**Fail** Front Service brake excessively fluctuating (1.2.1 (e))**MOT #6** 2019-10-23 07:51**MOT test number** 771363109236**Result** ✓ Passed

**MOT #5** 2019-10-23 07:51**MOT test number** 984612594516**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**MOT #4** 2018-10-02 16:26**MOT test number** 271249365795**Result** ✓ Passed**MOT #3** 2018-10-02 09:20**MOT test number** 698687722085**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Nail in tyre**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #2** 2017-09-19 11:25**MOT test number** 162962840798**Result** ✓ Passed**MOT #1** 2016-06-30 09:42**MOT test number** 170179736977**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
22 August 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	22 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-08-14
Last registration	2023-07-29
Complete history	See info



Registration #1	2013-08-14	26 mi
Registration #2	2016-06-30	64.180 mi
Registration #3	2017-09-19	74.342 mi
Registration #4	2018-10-02	81.110 mi
Registration #5	2018-10-02	81.112 mi
Registration #6	2019-10-23	86.455 mi
Registration #7	2019-10-23	86.455 mi
Registration #8	2021-01-06	92.128 mi
Registration #9	2023-07-29	150.000 mi
Registration #10	2023-07-29	150.000 mi
Registration #11	2023-07-29	150.000 mi
Registration #12	2023-07-29	150.000 mi
Registration #13	2023-07-29	150.000 mi
Registration #14	2023-07-29	150.000 mi
Registration #15	2023-07-29	150.000 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1605 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	1259958
---------------	---------