



report date: 2024-03-29

General information

Make	JAGUAR
Model	S-TYPE V6 SE
Colour	Black
Year of manufacture	2005
Top speed	145 mph
0 - 60 mph	7.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	299 Nm at 4.100 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Petrol
Consumption city	18.5 mpg
Consumption extra urban	35.3 mpg
Consumption combined	26.4 mpg
CO2 emission	259 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-08-02
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-20
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	66
Total items failed	8

MOT #22	2023-12-06 09:53
MOT test number	377266292541
Result	✓ Passed
Next expiry date	2024-12-20

MOT #21	2022-12-20 13:45
MOT test number	642055649207
Result	✓ Passed

MOT #20	2021-12-21 14:59
MOT test number	147623799048
Result	✓ Passed

Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #19	2021-12-20 16:34
MOT test number	303533179332

Result	✗ Failed
--------	----------

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #18**

2021-05-06 14:12

MOT test number

834720163365

Result

✓ Passed

- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge bald and showing signs of ageing/cracking (5.2.3 (e))
- Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement outer bush (5.3.4 (a) (i))
- Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement inner rear bush (5.3.4 (a) (i))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened pitted (1.1.14 (a) (ii))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inner edge bald and showing signs of ageing/cracking (5.2.3 (e))
- Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement outer bush (5.3.4 (a) (i))
- Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement inner rear bush (5.3.4 (a) (i))

**MOT #17**

2021-05-04 09:06

MOT test number

530840892302

Result**✗ Failed**

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement inner rear bush (5.3.4 (a) (i))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Nearside Headlamp not working on dipped beam Tried new bulb but still not working! (4.1.1 (a) (ii))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge bald and showing signs of ageing/cracking (5.2.3 (e))
- Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement outer bush (5.3.4 (a) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened pitted (1.1.14 (a) (ii))
- Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement inner rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Nearside Headlamp aim not tested NOTE. Headlamp reflector broken/adrift from adjusters (4.1.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge bald and tyre ageing/cracking (5.2.3 (e))
- Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement outer bush (5.3.4 (a) (i))

MOT #16

2020-05-22 13:14

MOT test number

453894845602

Result**✓ Passed**

- Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #15**

2019-05-13 10:37

MOT test number

554770616737

Result

✓ Passed

Advice Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement outer (5.3.4 (a) (i))

Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement outer (5.3.4 (a) (i))

Advice Offside Rear Nail in tyre

Advice Nearside Front Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #14

2018-05-09 09:44

MOT test number

654496849443

Result

✓ Passed

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #13

2017-05-08 08:36

MOT test number

195745712249

Result

✓ Passed

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Rear Lower Suspension arm has slight play in a pin/bush Inner and outer bush (2.4.G.2)

Advice Nearside Rear Lower Suspension arm has slight play in a pin/bush Inner and outer bush (2.4.G.2)

MOT #12

2016-05-09 09:33

MOT test number

996656101221

Result

✓ Passed

Advice Offside Rear Lower Suspension arm has slight play in a pin/bush inner and outer bush (2.4.G.2)

Advice Nearside Rear Lower Suspension arm has slight play in a pin/bush inner and outer bush (2.4.G.2)

**MOT #11**

2015-05-06 09:47

MOT test number

467196125179

Result

✓ Passed

Advice Power steering component(s) has slight seepage from a component (2.3.3b)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #10**

2015-05-06 09:47

MOT test number

826746725199

Result

✗ Failed

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Power steering component(s) has slight seepage from a component (2.3.3b)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #9**

2014-05-09 17:00

MOT test number

649939824110

Result

✓ Passed

Advice Nearside Front Lower Shock absorber has a slightly worn bush (2.7.4)**Advice** Nearside Front Upper Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)**Advice** Offside Rear Lower Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**MOT #8**

2014-05-09 17:00

MOT test number

827819124143

Result

✗ Failed

Pass with rectification Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Lower Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Lower Shock absorber has a slightly worn bush (2.7.4)**Advice** Nearside Front Upper Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)**MOT #7**

2013-05-13 14:26

MOT test number

937163933196

Result

✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Lower Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside Front Lower Shock absorber has a slightly worn bush (2.7.4)**MOT #6**

2013-05-13 14:26

MOT test number

399083733157

Result

✗ Failed

Pass with rectification Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Lower Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside Front Lower Shock absorber has a slightly worn bush (2.7.4)**MOT #5**

2012-05-10 13:21

MOT test number

139171332161

Result

✓ Passed

**MOT #4** 2011-05-10 15:15**MOT test number** 945610731198**Result** ✓ Passed**MOT #3** 2010-05-18 15:14**MOT test number** 303598530134**Result** ✓ Passed**Notice** Nearside rear tyre has damage deep enough to reach the cords but less than 25mm.**MOT #2** 2009-06-02 17:46**MOT test number** 283153659167**Result** ✓ Passed**MOT #1** 2008-05-06 15:55**MOT test number** 281167628175**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
20 December 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	20 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-05-27
Last registration	2023-12-06
Complete history	See info



Registration #1	2005-05-27	14 mi
Registration #2	2008-05-06	31.589 mi
Registration #3	2009-06-02	32.952 mi
Registration #4	2010-05-18	37.898 mi
Registration #5	2011-05-10	43.516 mi
Registration #6	2012-05-10	48.750 mi
Registration #7	2013-05-13	54.325 mi
Registration #8	2014-05-09	59.500 mi
Registration #9	2015-05-06	64.883 mi
Registration #10	2016-05-09	79.103 mi
Registration #11	2017-05-08	74.804 mi
Registration #12	2018-05-08	75.277 mi
Registration #13	2019-05-08	75.277 mi
Registration #14	2020-05-08	75.277 mi
Registration #15	2021-05-08	75.277 mi
Registration #16	2022-05-08	75.277 mi
Registration #17	2023-05-08	75.277 mi
Registration #18	2024-05-08	75.277 mi
Registration #19	2025-05-08	75.277 mi
Registration #20	2026-05-08	75.277 mi
Registration #21	2027-05-08	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2040 mm
Height	1444 mm
Length	4861 mm
Wheel base	2909 mm
Kerb weight	1710 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	69 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	499683357FB