



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 R-DESIGN
Colour	White
Year of manufacture	2010
Top speed	115 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-08-19
Pictures	21
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-03
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	46
Total items failed	3

MOT #15	2023-07-24 07:53
MOT test number	563822102760
Result	✓ Passed
Next expiry date	2024-08-03
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Front Power steering pipe/hose slightly corroded (2.1.5 (g) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))



MOT #14

2022-07-28 15:36

MOT test number

703170875611

Result

✓ Passed

- Advice

Front Suspension arm pin or bush worn but not resulting in excessive movement Both sides (5.3.4 (a) (i))
- Advice

Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Rear Brake hose has slight corrosion to ferrule Both sides (1.1.12 (f) (i))
- Advice

Front Power steering pipe/hose slightly corroded (2.1.5 (g) (i))
- Advice

Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice

Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Rear Suspension arm corroded but not seriously weakened Both sides (5.3.3 (b) (i))
- Advice

Rear Brake pipe joiner corroded
- Advice

Nearside Front Power steering ram has slight seepage from a joint Steering rack (2.1.5 (a))

**MOT #13**

2022-07-27 13:12

MOT test number

987515225912

Result**✗ Failed****MAJOR** Nearside Rear All direction indicators incorrect colour (4.4.3 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Rear Brake pipe joiner corroded**Advice** Offside Rear Tyre slightly damaged/cracking or perishing Deep cracking near limit (5.2.3 (d) (ii))**Advice** Rear Suspension arm corroded but not seriously weakened Both sides (5.3.3 (b) (i))**Advice** Nearside Front Power steering ram has slight seepage from a joint Steering rack (2.1.5 (a))**Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement Both sides (5.3.4 (a) (i))**Advice** Rear Tyre worn close to legal limit/worn on edge Both sides (5.2.3 (e))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Brake hose has slight corrosion to ferrule Both sides (1.1.12 (f) (i))**Advice** Front Power steering pipe/hose slightly corroded (2.1.5 (g) (i))**MOT #12**

2021-07-20 12:06

MOT test number

296948184452

Result**✓ Passed****Advice** Oil leak**Advice** All 4 brake discs corroded**Advice** Rear sub frame and suspension arms corroded

**MOT #11**

2020-07-23 11:22

MOT test number

653392446220

Result

✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Slight oil leak

MOT #10

2020-07-23 11:22

MOT test number

479925638270

Result

✗ Failed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Pass with rectification Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Slight oil leak

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Pass with rectification Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #9

2019-07-04 13:44

MOT test number

669110737134

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8

2018-07-09 10:40

MOT test number

751932264025

Result

✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #7** 2018-07-06 09:05**MOT test number** 980424358825**Result** ✗ Failed**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm inner (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #6** 2017-07-18 10:59**MOT test number** 310685071768**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**Advice** Oil leak under engine.**MOT #5** 2017-07-18 08:07**MOT test number** 177747783427**Result** ✗ Failed**Advice** Offside Rear Nail in tyre**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Oil leak under engine.**MOT #4** 2016-07-29 09:08**MOT test number** 104474240347**Result** ✓ Passed**MOT #3** 2015-07-31 13:09**MOT test number** 566552415243**Result** ✓ Passed



MOT #2	2014-08-04 10:01
MOT test number	176166314294
Result	✓ Passed
Advice	Brake pad(s) wearing thin (3.5.1g)

MOT #1	2013-07-30 17:09
MOT test number	209141113271
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
3 August 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	3 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-07-26
Last registration	2023-07-24
Complete history	See info



Registration #1	2010-07-26	9 mi
Registration #2	2013-07-30	30.929 mi
Registration #3	2014-08-04	37.196 mi
Registration #4	2015-07-31	43.321 mi
Registration #5	2016-07-29	48.873 mi
Registration #6	2017-07-18	53.124 mi
Registration #7	2017-07-18	53.124 mi
Registration #8	2018-07-06	55.226 mi
Registration #9	2018-07-09	55.226 mi
Registration #10	2019-06-20	55.226 mi
Registration #11	2019-06-20	55.226 mi
Registration #12	2019-06-20	55.226 mi
Registration #13	2019-06-20	55.226 mi
Registration #14	2019-06-20	55.226 mi
Registration #15	2019-06-20	55.226 mi
Registration #16	2019-06-20	55.226 mi
Registration #17	2019-06-20	55.226 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1299 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	181935