





report date: 2024-03-29

#### General information

Make	CITROEN
Model	C1 PURETECH FLAIR
Colour	White
Year of manufacture	2018
Top speed	106 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	82 BHP
Max. torque	116 Nm at 2.750 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	52.3 mpg
Consumption extra urban	76.4 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	Α



CarCheck.co.uk page 1/12



report date: 2024-03-29

### Internet history

#### Entry 2

Date 2021-01-29

Pictures 10

Listing price <u>View report</u>










source: autoonline.co.uk


#### Entry 1

Date	2021-01-21
Pictures	21

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



report date: 2024-03-29

N/I	$\alpha$		uc:	t۸	r\/
101	•		115	w	ıv
	•	Γh			. ,

MOT expiry date	2025-02-04
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	24
Total items failed	0

MOT #6		2024-01-30 09:37
MOT test	number	374577869682
Result		✓ Passed
Next expi	ry date	2025-02-04
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Oil leak, but not excessive drive shaft oil seal area (8.4.1 (a) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Items removed from driver's view prior to test	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement bush		
(5.3.4 (a) (	i))	
Advice	TPMS lamp illuminated	

CarCheck.co.uk page 3/12



report date: 2024-03-29

152913979327

**MOT #5** 2024-01-27 12:34

**MOT test number** 511027789684

**Result** X Failed

**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** TPMS lamp illuminated

**MOT** test number

Advice Nearside Front Oil leak, but not excessive drive shaft oil seal area (8.4.1 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Items removed from driver's view prior to test

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement bush (5.3.4 (a) (i))

MOT #4 2023-01-21 12:17

Advice Nearside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #3		2023-01-21 10:03
MOT test	number	446381997139
Result		<b>×</b> Failed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii)	))
MAJOR	Rear Exhaust silencer insecure (8.1.1 (b) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (	e))

MOT #2	2022-01-29 11:36
MOT test number	586124337362
Result	<b>✓</b> Passed
MOT #1	2021-02-05 14:26
MOT test number	580250259194
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	4 February 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	E
First licence fee (12 months)	£ 165,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	
***********	
***************************************	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	UK ZIN
Plate since	
Current registration	NK NY
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-01-19
Last registration	2024-01-30
Complete history	See info



Registration #1	2018-01-19	25 mi
Registration #2		11.777 es
Registration #3		11.777 es
Registration #4	2021-02-05	29.554 mi
Registration #5	2022-01-29	34.401 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 esi

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

## Safety ratings

NCAP rating	<b>大大大</b> 大大
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



## Dimensions & weight

Width	1615 mm
Height	1460 mm
Length	3465 mm
Wheel base	2340 mm
Kerb weight	865 kg
Max. allowed weight	1240 kg

## Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	B2220061493

CarCheck.co.uk page 12/12