



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	CELICA VVTI BLUE
Colour	Silver
Year of manufacture	2005
Top speed	127 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	172 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history


Entry 2

Date	2022-04-29
Pictures	0
Listing price	<a href="#">View report</a>

source: [cargurus.co.uk](#)

Entry 1

Date	2021-10-19
Pictures	5
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2025-02-28
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	29
Total items failed	13

MOT #22	2024-02-29 10:33
MOT test number	587869944808
Result	✓ Passed
Next expiry date	2025-02-28
Advice	Heavily undersealed

MOT #21	2024-02-22 16:20
MOT test number	397195545042
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Heavily undersealed
Fail	Nearside Rear Inner Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting sill (6.2.2 (d) (i))

MOT #20	2022-06-10 16:23
MOT test number	756680182896
Result	✓ Passed
Advice	Underbody corrosion through out

**MOT #19**

2022-06-09 14:57

**MOT test number**

431464213675

**Result**

✗ Failed

**Fail** Offside Rear Vehicle structure inadequately repaired such that structural rigidity is significantly reduced rear inner wheel arch (6.1.1 (d) (i))

**Advice** Underbody corrosion through out

**Fail** Nearside Rear Service brake effort inadequate at a wheel (1.2.1 (a) (i))

**MOT #18**

2021-12-17 09:23

**MOT test number**

964194924398

**Result**

✗ Failed

**Fail** Offside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength wheel arch (5.3.6 (a) (i))

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Fail** Nearside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength wheel arch (5.3.6 (a) (i))

**Advice** Under body and suspension rusty

**MOT #17**

2020-11-18 10:12

**MOT test number**

706964679417

**Result**

✓ Passed

**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #16**

2019-11-08 15:25

**MOT test number**

376838284560

**Result**

✓ Passed

**Advice** Offside Rear Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**MOT #15**

2019-11-07 10:20

**MOT test number**

147973265363

**Result****✗ Failed****Advice**

Offside Rear Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**Fail**

Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**Advice**

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14**

2018-11-22 14:01

**MOT test number**

501700784491

**Result****✓ Passed****MOT #13**

2018-10-31 10:41

**MOT test number**

790375662009

**Result****✗ Failed****Fail**

Nearside Rear Fuel pipe leaking filler pipe (6.1.3 (b) (i))

**Fail**

Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**Fail**

Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

**MOT #12**

2017-10-25 13:45

**MOT test number**

651761097088

**Result****✓ Passed****Advice**

Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

**Advice**

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice**

Offside Rear Brake pipe slightly corroded (3.6.B.2c)



<b>MOT #11</b>	2016-10-25 11:32
<b>MOT test number</b>	610292586641
<b>Result</b>	✓ Passed
<b>Advice</b>	Filler neck corroded

<b>MOT #10</b>	2015-10-21 09:26
<b>MOT test number</b>	668834470851
<b>Result</b>	✓ Passed

<b>MOT #9</b>	2014-10-14 15:51
<b>MOT test number</b>	447067284211
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Exhaust has a minor leak of exhaust gases (7.1.2)
<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Rear registration plate deteriorated but not likely to be misread (6.3.1d)
<b>Advice</b>	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
<b>Advice</b>	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Front registration plate deteriorated but not likely to be misread (6.3.1d)
<b>Advice</b>	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

<b>MOT #8</b>	2013-10-22 16:48
<b>MOT test number</b>	967475193261
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2012-10-23 12:42**MOT test number** 589487692273**Result** ✓ Passed**MOT #6** 2011-10-21 14:20**MOT test number** 516464591269**Result** ✓ Passed**MOT #5** 2010-10-26 14:24**MOT test number** 583559890240**Result** ✓ Passed**MOT #4** 2010-10-26 14:24**MOT test number** 761389890296**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #3** 2009-10-27 10:00**MOT test number** 841220009396**Result** ✓ Passed**MOT #2** 2009-10-26 16:50**MOT test number** 472509399248**Result** ✗ Failed**Fail** Brakes imbalanced across an axle (3.7.B.5b)**Fail** Service brake: efficiency below requirements (3.7.B.7)



MOT #1	2008-10-27 14:03
MOT test number	990781108371
Result	✓ Passed
Advice	Front brake disc slightly pitted (3.5.1h)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Rear brake disc slightly pitted (3.5.1h)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
28 February 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	28 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history


Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	<b>XXXX XX</b>
Plate since	2024-03-28
Current registration	<b>XXXX XX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-10-31
Last registration	2024-02-29
Complete history	<a href="#">See info</a>



Registration #1	2005-10-31	10 mi
Registration #2	2008-10-27	28.264 mi
Registration #3	2009-10-26	31.378 mi
Registration #4	2009-10-27	31.378 mi
Registration #5	2010-10-26	34.804 mi
Registration #6	2011-10-21	36.916 mi
Registration #7	2012-10-23	39.114 mi
Registration #8	2013-10-22	42.535 mi
Registration #9	2014-10-14	45.161 mi
Registration #10	2015-10-21	47.901 mi
Registration #11	2016-10-25	49.687 mi
Registration #12	2017-10-25	50.903 mi
Registration #13	2018-10-29	52.119 mi
Registration #14	2019-10-29	53.335 mi
Registration #15	2020-10-29	54.551 mi
Registration #16	2021-10-29	55.767 mi
Registration #17	2022-10-29	56.983 mi
Registration #18	2023-10-29	58.199 mi
Registration #19	2024-02-29	59.415 mi
Registration #20		
Registration #21		
Registration #22		
Registration #23		
Registration #24		

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1735 mm
Height	1315 mm
Length	4350 mm
Wheel base	2600 mm
Kerb weight	1145 kg
Max. allowed weight	1565 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	1ZZ2317949