



report date: 2024-03-28

General information

Make	CITROEN
Model	BERLINGO 625 X L1 HDI
Colour	White
Year of manufacture	2014
Top speed	99 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	215 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	60.1 mpg
Consumption combined	56.5 mpg
CO2 emission	132 g/km
CO2 label	E





MOT history

MOT expiry date	2025-02-08
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	26
Total items failed	3

MOT #14	2024-01-31 16:47
MOT test number	263115919559
Result	✓ Passed
Next expiry date	2025-02-08

MOT #13	2024-01-31 11:42
MOT test number	827227385783
Result	✗ Failed

- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- MAJOR** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- DANGEROUS** Offside Front Anti-roll bar linkage insecure and impairing directional stability (5.3.3 (a) (ii))
- MAJOR** Horn not working (7.7 (a))
- MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #12	2023-02-08 14:26
MOT test number	401100712716
Result	✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2023-02-08 14:26

MOT test number

873792451459

Result**✗ Failed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10**

2022-02-01 16:31

MOT test number

140391104993

Result**✓ Passed****Advice** Front position lamps not a matched pair**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Body component slightly loose Head lamp (6.2.1 (a) (i))**Advice** Front indicators on a matched pair**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9**

2022-02-01 11:57

MOT test number

222583886033

Result**✗ Failed****MAJOR** Nearside Headlamp aim too low (4.1.2 (a))**MAJOR** Offside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))**Advice** Front position lamps not a matched pair**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Headlamp aim too high (4.1.2 (a))**Advice** Nearside Front Body component slightly loose Head lamp (6.2.1 (a) (i))**Advice** Front indicators on a matched pair

**MOT #8** 2021-02-09 11:05**MOT test number** 334008342373**Result** ✓ Passed**Advice** Nearside Front Wheel splash missing**Advice** Central Front Undertray missing**MOT #7** 2021-02-02 10:43**MOT test number** 858275822450**Result** ✗ Failed**Advice** Nearside Front Wheel splash missing**Advice** Central Front Undertray missing**DANGEROUS** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure Tread missing over center of the tyre (5.2.3 (d) (ii))**MOT #6** 2020-10-23 10:52**MOT test number** 820700632707**Result** ✓ Passed**MOT #5** 2019-10-26 08:29**MOT test number** 408034696367**Result** ✓ Passed**MOT #4** 2018-11-06 13:23**MOT test number** 340840870222**Result** ✓ Passed**MOT #3** 2018-06-05 13:26**MOT test number** 437807666719**Result** ✓ Passed



MOT #2	2018-06-05 13:26
MOT test number	116439574750
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))

MOT #1	2017-08-30 07:34
MOT test number	254602461998
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
8 February 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	8 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 BD64SPZ
Plate since	2019-09-29
Current registration	 BD64SPZ
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-11-24
Last registration	2024-01-31
Complete history	See info



Registration #1	2014-11-24	22 mi
Registration #2	2017-08-30	57.259 mi
Registration #3	2018-06-05	75.276 mi
Registration #4	2018-06-05	75.276 mi
Registration #5	2018-11-06	86.663 mi
Registration #6	2019-10-26	99.136 mi
Registration #7	2020-10-23	111.473 mi
Registration #8	2021-02-02	113.008 mi
Registration #9	2022-05-20	113.008 mi
Registration #10	2022-05-20	113.008 mi
Registration #11	2022-05-20	113.008 mi
Registration #12	2022-05-20	113.008 mi
Registration #13	2022-05-20	113.008 mi
Registration #14	2022-05-20	113.008 mi
Registration #15	2022-05-20	113.008 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1801 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1289 kg
Max. allowed weight	1960 kg

Additional information

Fuel delivery	Direct Injection
Number of seats	2
Number of axles	2
Engine number	JBEM0326604