



report date: 2024-03-28

General information

Make	MINI
Model	MINI (R60) COOPER SD
Colour	Blue
Year of manufacture	2012
Top speed	123 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	61.4 mpg
CO2 emission	122 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-02-02
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)

**MOT history**

<b>MOT expiry date</b>	2025-01-05
<b>MOT pass rate</b>	77 %
<b>MOT passed</b>	10
<b>Failed MOT tests</b>	3
<b>Total advice items</b>	20
<b>Total items failed</b>	5

<b>MOT #13</b>	2023-12-12 08:50
<b>MOT test number</b>	231109341943
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2025-01-05
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))

<b>MOT #12</b>	2023-01-06 10:39
<b>MOT test number</b>	287055934461
<b>Result</b>	✓ Passed
<b>Advice</b>	Too clean to smoke test

<b>MOT #11</b>	2023-01-06 10:39
<b>MOT test number</b>	962558987960
<b>Result</b>	✗ Failed
<b>Advice</b>	Too clean to smoke test
<b>Pass with rectification</b>	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #10** 2022-01-04 10:30**MOT test number** 898633104385**Result** ✓ Passed**Advice** Too clean to smoke test**Advice** Offside Front Suspension arm attachment bracket/mounting damaged but its strength is not seriously reduced (5.3.3 (b) (i))**MOT #9** 2021-01-02 18:51**MOT test number** 347746794632**Result** ✓ Passed**MOT #8** 2020-02-26 14:19**MOT test number** 995948577102**Result** ✓ Passed**Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Advice** Nearside rear outer brake pad has been fitted upside down**MOT #7** 2020-02-25 11:13**MOT test number** 590036674066**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge tyre is on 1.6mm (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) (ii))**Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Advice** Nearside Rear Nail in tyre**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #6** 2019-02-19 16:19**MOT test number** 296693065763**Result** ✓ Passed**MOT #5** 2018-01-05 10:42**MOT test number** 116132834175**Result** ✓ Passed**Advice** Non runflat tyres fitted to front wheels**MOT #4** 2017-06-09 11:25**MOT test number** 678736546646**Result** ✓ Passed**MOT #3** 2017-06-09 08:18**MOT test number** 370563229946**Result** ✗ Failed**Fail** Central Upper Stop lamp not working (1.2.1b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2016-05-28 11:04**MOT test number** 976492805662**Result** ✓ Passed



MOT #12015-06-13 11:33

MOT test number965144065109

Result

✓ Passed

- Notice

Under-trays fitted obscuring some underside components
- Notice

Unable to check brake pads (possible worn)
- Notice

Child seat fitted not allowing full inspection of adult belt
- Notice

Engine covers fitted obscuring some components in the engine bay
- Notice

None run flat tyre fitted n/s rear



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
5 January 2025

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	5 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-06-15
Last registration	2023-12-12
Complete history	<a href="#">See info</a>



Registration #1	2012-06-15	11 mi
Registration #2	2015-06-13	34.755 mi
Registration #3	2016-05-28	42.135 mi
Registration #4	2017-06-09	50.060 mi
Registration #5	2017-06-09	50.060 mi
Registration #6	2018-01-05	53.905 mi
Registration #7	2019-02-19	59.390 mi
Registration #8	2020-02-25	65.417 mi
Registration #9	2020-02-25	65.417 mi
Registration #10	2020-02-25	65.417 mi
Registration #11	2020-02-25	65.417 mi
Registration #12	2020-02-25	65.417 mi
Registration #13	2020-02-25	65.417 mi
Registration #14	2020-02-25	65.417 mi
Registration #15	2020-02-25	65.417 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1320 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

72588135