



EX5IRUU


report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE
Colour	Red
Year of manufacture	2001
Gearbox	-

Engine & fuel consumption

Engine capacity	1.984 cc
Fuel type	Petrol
CO2 emission	228 g/km
CO2 label	L





MOT history

MOT expiry date	2024-07-26
MOT pass rate	78 %
MOT passed	18
Failed MOT tests	5
Total advice items	44
Total items failed	6

MOT #23	2023-07-27 16:58
---------	------------------

MOT test number	497179248256
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-07-26
------------------	------------

- Advice

Nearside Front Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor

Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated insecure at the end clip (6.1.7 (g) (i))
- Advice

Oil leak, but not excessive underneath (8.4.1 (a) (i))
- Minor

Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice

Nearside front quarter panel damaged due to impact
- Advice

Offside Front Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor

Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated at the end clip (6.1.7 (g) (i))



MOT #22

2023-07-27 16:58

MOT test number

879461470886

Result

✗ Failed

Pass with rectification

Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

Advice

Offside Front Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor

Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated at the end clip (6.1.7 (g) (i))

Advice

Nearside front quarter panel damaged due to impact

Advice

Nearside Front Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor

Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated insecure at the end clip (6.1.7 (g) (i))

Advice

Oil leak, but not excessive underneath (8.4.1 (a) (i))

Minor

Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))

**MOT #21**

2023-07-22 10:09

**MOT test number**

877190653015

**Result****✗ Failed****MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Offside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Offside Front Inner Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Some damage to outer sills**MAJOR** Nearside Front Inner Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))**MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**MOT #20**

2022-07-25 12:24

**MOT test number**

862902509151

**Result****✓ Passed****Advice** Some surface corrosion to offside front outer sill**Advice** Offside Front Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Inner Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #19** 2022-07-21 12:22**MOT test number** 797483547310**Result** ✗ Failed**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**MAJOR** Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #18** 2021-07-15 14:15**MOT test number** 962438039563**Result** ✓ Passed**Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #17** 2020-07-23 14:27**MOT test number** 992248500814**Result** ✓ Passed**MOT #16** 2019-07-16 15:13**MOT test number** 414140147295**Result** ✓ Passed**MOT #15** 2018-07-24 14:27**MOT test number** 533621072346**Result** ✓ Passed



<b>MOT #14</b>	2017-08-23 16:08
----------------	------------------

<b>MOT test number</b>	213960160068
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #13</b>	2016-08-16 12:29
----------------	------------------

<b>MOT test number</b>	874519416643
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Supplementary Restraint System warning lamp does not illuminate (5.4.2)
---------------	---

<b>MOT #12</b>	2015-08-12 14:08
----------------	------------------

<b>MOT test number</b>	619548872510
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #11</b>	2014-08-14 14:51
----------------	------------------

<b>MOT test number</b>	418566124270
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #10</b>	2013-08-14 15:51
----------------	------------------

<b>MOT test number</b>	988106423238
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #9</b>	2012-08-20 16:18
---------------	------------------

<b>MOT test number</b>	279233132299
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #8</b>	2011-08-17 15:03
---------------	------------------

<b>MOT test number</b>	447939821234
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

**MOT #7** 2010-08-12 11:16**MOT test number** 641434120258**Result** Passed**MOT #6** 2009-08-14 15:52**MOT test number** 332296529494**Result** Failed**Notice** The front tyres are starting to wear on the edges.**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Notice** The rear tyre are feathering on the edges.**MOT #5** 2009-08-14 15:52**MOT test number** 810346829287**Result** Passed**Notice** The rear tyre are feathering on the edges.**Notice** The front tyres are starting to wear on the edges.**MOT #4** 2008-08-18 11:56**MOT test number** 712831438283**Result** Passed**Notice** Both front wheels have slight play



MOT #3	2008-08-18 09:20
MOT test number	722111138280
Result	✗ Failed
Fail	Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)
Fail	Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)
Fail	Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)
Notice	Both front wheels have slight play
Fail	Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

MOT #2	2007-08-23 09:14
MOT test number	192155337233
Result	✓ Passed

MOT #1	2006-08-29 12:37
MOT test number	370771846489
Result	✓ Passed





Tax & MOT check

X

Untaxed

Tax expired:  
1 July 2023

✓

MOT

Expires:  
26 July 2024

Tax status	Expired at 1 July 2023
Days left	303 days too late
MOT expiry date	26 July 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 EX51RUU
Plate since	2024-03-29
Current registration	 EX51RUU
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2001-09-01
Last registration	2023-07-27
Complete history	<a href="#">See info</a>



Registration #1	2001-09-01	28 mi
Registration #2	2006-08-29	54.630 mi
Registration #3	2007-08-23	63.465 mi
Registration #4	2008-08-18	69.883 mi
Registration #5	2008-08-18	69.883 mi
Registration #6	2009-08-14	74.197 mi
Registration #7	2010-08-12	77.368 mi
Registration #8	2011-08-17	81.274 mi
Registration #9	2012-08-20	83.820 mi
Registration #10	2013-08-14	85.990 mi
Registration #11	2014-08-14	87.394 mi
Registration #12	2015-08-12	89.267 mi
Registration #13	2016-08-12	91.140 mi
Registration #14	2017-08-12	93.013 mi
Registration #15	2018-08-12	94.886 mi
Registration #16	2019-08-12	96.759 mi
Registration #17	2020-08-12	98.632 mi
Registration #18	2021-08-12	100.505 mi
Registration #19	2022-08-12	102.378 mi
Registration #20	2023-08-12	104.251 mi
Registration #21	2024-08-12	106.124 mi
Registration #22	2025-08-12	108.000 mi
Registration #23	2026-08-12	110.000 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Engine number NOT KNOWN