



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Red
Year of manufacture	2003
Top speed	111 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-07-14
Pictures	1
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-17
MOT pass rate	67 %
MOT passed	18
Failed MOT tests	9
Total advice items	70
Total items failed	22

MOT #27	2023-08-18 11:18
MOT test number	736049146376
Result	✓ Passed
Next expiry date	2024-08-17
Advice	Central Rear Spare tyre defective Semi flat
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Central Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #26**

2023-08-14 16:54

**MOT test number**

946827784661

**Result**

✗ Failed

- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Central Rear Spare tyre defective Semi flat
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Front Headlamp aim unable to be tested Headlamp not working on dipped beam (4.1.2 (b))
- Fail** Nearside Front Lower Direction indicator incorrect colour (4.4.3 (a))
- Advice** Central Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Offside Front Headlamp aim unable to be tested Headlamp not working on dipped beam (4.1.2 (b))
- Fail** Offside Front Lower Direction indicator incorrect colour (4.4.3 (a))

**MOT #25**

2022-08-09 11:36

**MOT test number**

561137911299

**Result**

✓ Passed

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing in tread (5.2.3 (d) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #24**

2021-08-12 07:28

**MOT test number**

642760137932

**Result**

✓ Passed

**MOT #23** 2021-08-11 12:43**MOT test number** 352521158583**Result** ✗ Failed**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #22** 2020-11-25 12:15**MOT test number** 333832898869**Result** ✓ Passed**MOT #21** 2019-11-08 08:44**MOT test number** 693160318469**Result** ✓ Passed**MOT #20** 2018-11-19 15:28**MOT test number** 199562568469**Result** ✓ Passed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front All direction indicators slightly discoloured (4.4.3 (a))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #19**

2017-12-01 14:57

**MOT test number**

981406931313

**Result**

✓ Passed

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Nail in tyre**Advice** Offside slight cracking on tyre treads**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Outer cracking on front and rear tyre walls**MOT #18**

2017-11-20 14:47

**MOT test number**

200997612976

**Result**

✗ Failed

**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Offside slight cracking on tyre treads**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Nearside Rear Nail in tyre**Advice** Offside Outer cracking on front and rear tyre walls

**MOT #17** 2016-11-28 14:06**MOT test number** 318227403512**Result** ✓ Passed

- Advice** Front Outer cracking on tyre treads
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front Direction indicators slightly discoloured (1.4.A.2f)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #16** 2016-11-28 14:06**MOT test number** 881954567052**Result** ✗ Failed

- Advice** Front Direction indicators slightly discoloured (1.4.A.2f)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Pass with rectification** Offside Headlamp aim too high (1.8)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front Outer cracking on tyre treads
- Pass with rectification** Nearside Headlamp aim too high (1.8)

**MOT #15**

2015-11-23 13:48

**MOT test number**

582452452539

**Result**

✓ Passed

- Advice** Front Outer Slight cracking on tyre treads
- Advice** Nearside Rear Nail in tyre tread
- Advice** Front Direction indicators slightly discoloured (1.4.A.2f)
- Advice** Offside Rear Sub-frame attachment rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear Nail in tyre tread
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Sub-frame attachment rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #14**

2015-11-23 13:48

**MOT test number**

807563735242

**Result**

✗ Failed

- Advice** Front Direction indicators slightly discoloured (1.4.A.2f)
- Advice** Offside Rear Sub-frame attachment rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Front Outer Slight cracking on tyre treads
- Advice** Nearside Rear Nail in tyre tread
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Sub-frame attachment rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear Nail in tyre tread
- Pass with rectification** Nearside Stop lamp not working (1.2.1b)



**MOT #13** 2014-11-24 15:36**MOT test number** 438468924439**Result** ✓ Passed

**Advice** Nearside Outer Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

**Notice** Cracking on n/s outer tyre wall.

**Advice** Front Direction indicators slightly discoloured (1.4.A.2f)

**Notice** Slight cracking on n/s o/s rear outer tyre walls.

**MOT #12** 2014-11-24 15:36**MOT test number** 585468524375**Result** ✗ Failed

**Pass with rectification** Offside Headlamp aim too far to the left (1.8)

**Advice** Nearside Outer Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

**Notice** Cracking on n/s outer tyre wall.

**Pass with rectification** Nearside Headlamp aim too far to the left (1.8)

**Advice** Front Direction indicators slightly discoloured (1.4.A.2f)

**Notice** Slight cracking on n/s o/s rear outer tyre walls.

**MOT #11** 2013-11-25 12:51**MOT test number** 889449523390**Result** ✓ Passed

**MOT #10** 2013-11-12 13:06**MOT test number** 527626213390**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Notice** Offside front tyre perishing outer wall**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Driver's airbag obviously defective (5.4.1)**MOT #9** 2012-11-05 11:39**MOT test number** 928430812380**Result** ✓ Passed**Notice** Air bag light on**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #8** 2011-11-01 10:55**MOT test number** 497875901419**Result** ✓ Passed**Notice** Air bag light on**Notice** Front brake discs slight lip**MOT #7** 2010-10-11 12:11**MOT test number** 723554680257**Result** ✓ Passed**Notice** Offside front brake discs corroded inner edge**Notice** Air bag light on**Notice** Nearside front brake discs corroded inner edge

**MOT #6** 2009-09-10 12:37**MOT test number** 364713759441**Result** Passed**MOT #5** 2009-09-07 09:20**MOT test number** 354420259280**Result** Failed**Fail** Exhaust system not adequately supported (7.1.1)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Notice** Nail in offside front tyre**Fail** Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #4** 2008-07-30 12:32**MOT test number** 283432418258**Result** Passed**Notice** New number plates stuck over the top of old ones, ok at time of test.**MOT #3** 2008-07-29 16:31**MOT test number** 101531218231**Result** Failed**Fail** Rear registration plate character(s) incorrectly spaced (6.3.4a)**Notice** All four tyres perished and splitting**Fail** Front registration plate character(s) incorrectly spaced (6.3.4a)**MOT #2** 2007-07-30 10:37**MOT test number** 384381617489**Result** Passed



MOT #1	2006-07-31 10:27
MOT test number	822212216284
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
17 August 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	17 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2003-07-25
Last registration	2023-08-18
Complete history	<a href="#">See info</a>



Registration #1	2003-07-25	6 mi
Registration #2	2006-07-31	13.482 mi
Registration #3	2007-07-30	19.295 mi
Registration #4	2008-07-29	26.258 mi
Registration #5	2008-07-30	26.258 mi
Registration #6	2009-09-07	31.069 mi
Registration #7	2009-09-10	31.069 mi
Registration #8	2010-10-11	37.731 mi
Registration #9	2011-11-01	40.841 mi
Registration #10	2012-11-05	44.021 mi
Registration #11	2013-11-12	46.973 mi
Registration #12	2013-11-25	46.973 mi
Registration #13	2014-11-24	50.175 mi
Registration #14	2015-11-23	54.310 mi
Registration #15	2016-05-20	55.377 mi
Registration #16	2016-05-20	55.377 mi
Registration #17	2016-05-20	55.377 mi
Registration #18	2016-05-20	55.377 mi
Registration #19	2016-05-20	55.377 mi
Registration #20	2016-05-20	55.377 mi
Registration #21	2016-05-20	55.377 mi
Registration #22	2016-05-20	55.377 mi
Registration #23	2016-05-20	55.377 mi
Registration #24	2016-05-20	55.377 mi
Registration #25	2016-05-20	55.377 mi
Registration #26	2016-05-20	55.377 mi

Registration #27	2023-25-27	25,277-462
Registration #28	2023-25-28	25,277-462

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Kerb weight	1385 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2

**Engine number**

BFS 009754