



General information

Make	VOLKSWAGEN
Model	GOLF GT TDI
Colour	Black
Year of manufacture	2009
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

MOT expiry date	2024-03-21
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	10
Total items failed	10

MOT #15	2023-03-22 08:45
MOT test number	598335457041
Result	✓ Passed
Next expiry date	2024-03-21
Advice	Front MAIN BEAM LEVER NOT STAYING ON.
Advice	UNDERTRAYS FITTED

MOT #14	2023-03-20 16:44
MOT test number	934909186669
Result	✗ Failed
Advice	Front MAIN BEAM LEVER NOT STAYING ON.
Fail	Headlamp aim unable to be tested (4.1.2 (b))
Fail	Rear Tyre tread depth below requirements of 1.6mm BOTH SIDES (5.2.3 (e))
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	UNDERTRAYS FITTED
Fail	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Offside Rear Direction indicator not working (4.4.1 (a) (ii))

**MOT #13** 2022-01-13 11:05**MOT test number** 742755295921**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #12** 2022-01-12 11:02**MOT test number** 420373797349**Result** ✗ Failed**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MOT #11** 2021-01-18 12:34**MOT test number** 763201310265**Result** ✓ Passed**MOT #10** 2020-03-03 11:37**MOT test number** 425590217384**Result** ✓ Passed**MOT #9** 2019-03-06 14:18**MOT test number** 435928146516**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #8** 2019-03-05 13:22**MOT test number** 791661891420**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Rear fog lamp not working (4.5.1 (a) (ii))**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #7** 2018-03-07 13:24**MOT test number** 742644724444**Result** ✓ Passed**MOT #6** 2017-06-22 09:53**MOT test number** 460220458506**Result** ✓ Passed**MOT #5** 2016-06-23 08:37**MOT test number** 915733259842**Result** ✓ Passed**MOT #4** 2015-06-23 10:35**MOT test number** 818024075168**Result** ✓ Passed**Notice** O/s rear brake binding slightly**MOT #3** 2014-06-17 09:14**MOT test number** 856288164112**Result** ✓ Passed**Notice** Front brake discs corroded



MOT #2	2013-06-04 10:33
MOT test number	189085553138
Result	✓ Passed
MOT #1	2012-06-19 09:55
MOT test number	177481572103
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✗
MOT
Expired:
21 March 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	21 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	PF09JGX
Plate since	2024-03-29
Current registration	PF09JGX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-06-30
Last registration	2023-03-22
Complete history	See info



Registration #1	2009-06-30	14 mi
Registration #2	2012-06-19	32.535 mi
Registration #3	2013-06-04	38.579 mi
Registration #4	2014-06-17	47.844 mi
Registration #5	2015-06-23	55.532 mi
Registration #6	2016-06-23	64.104 mi
Registration #7	2017-06-22	72.839 mi
Registration #8	2018-03-07	79.469 mi
Registration #9	2019-03-22	85.104 mi
Registration #10	2020-03-22	90.739 mi
Registration #11	2021-03-22	96.374 mi
Registration #12	2022-03-22	102.009 mi
Registration #13	2023-03-22	107.644 mi
Registration #14	2024-03-22	113.279 mi
Registration #15	2025-03-22	118.914 mi
Registration #16	2026-03-22	124.549 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1299 kg
Max. allowed weight	1910 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	CBA 494126