



report date: 2024-03-28

General information

Make	CITROEN
Model	NEMO 660 LX STOP AND START HDI
Colour	White
Year of manufacture	2011
Top speed	96 mph
0 - 60 mph	16.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-06-10
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-19
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	12
Total items failed	9

MOT #12 2023-06-12 10:02**MOT test number** 150400537364**Result** ✓ Passed**Next expiry date** 2024-06-19

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))
- Advice** Front Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))

MOT #11 2022-06-20 14:01**MOT test number** 150964236136**Result** ✓ Passed

- Advice** Both front tyres wearing on inner edge

MOT #10 2022-03-19 09:25**MOT test number** 954223297036**Result** ✓ Passed

- Advice** Oil leak
- Advice** Both front tyres worn close to limit on edges of tread
- Advice** Offside rear tyre perished

**MOT #9** 2021-03-19 10:40**MOT test number** 816254344122**Result** ✓ Passed**MOT #8** 2021-03-09 12:43**MOT test number** 536005441110**Result** ✗ Failed**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #7** 2019-05-17 08:19**MOT test number** 462120713990**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #6** 2018-05-18 09:00**MOT test number** 303313521942**Result** ✓ Passed

**MOT #5** 2018-05-16 12:05**MOT test number** 676708647784**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #4** 2017-03-29 13:58**MOT test number** 997772362761**Result** ✓ Passed**MOT #3** 2017-03-27 15:02**MOT test number** 414172821345**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**MOT #2** 2015-10-26 11:34**MOT test number** 137698198381**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2014-09-30 10:12**MOT test number** 569913674202**Result** ✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-07-29
Last registration	2023-06-12
Complete history	See info



Registration #1	2011-07-29	28 mi
Registration #2	2014-09-30	40.571 mi
Registration #3	2015-10-26	52.111 mi
Registration #4	2017-03-27	61.180 mi
Registration #5	2017-03-29	61.180 mi
Registration #6	2018-05-16	65.375 mi
Registration #7	2018-05-18	65.375 mi
Registration #8	2019-05-20	65.375 mi
Registration #9	2019-05-20	65.375 mi
Registration #10	2019-05-20	65.375 mi
Registration #11	2019-05-20	65.375 mi
Registration #12	2019-05-20	65.375 mi
Registration #13	2019-05-20	65.375 mi
Registration #14	2019-05-20	65.375 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	59%
Children	74%
Pedestrian	55%
Safety systems	29%
Overall rating	58%
Video	see crash video



Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	00013893419