



report date: 2024-03-28

General information

Make	AUDI
Model	A3 TDI SPORT
Colour	Grey
Year of manufacture	-
Top speed	121 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 2.500 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	56.5 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-06
Pictures	22
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #13	2023-04-12 14:47
MOT test number	141082962540
Result	✓ Passed
Next expiry date	2024-04-15

MOT #12	2022-04-06 08:36
MOT test number	489834228400
Result	✓ Passed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Under trays fitted preventing full inspection
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11	2021-04-16 11:14
MOT test number	988678813824
Result	✓ Passed

- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #10**

2020-09-09 09:21

MOT test number

549694103566

Result

✓ Passed

- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Front Tyre worn on inner edge
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #9

2019-09-05 15:17

MOT test number

464713728581

Result

✓ Passed

- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #8

2019-09-05 13:12

MOT test number

839070121919

Result

✗ Failed

- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Rear Nail in tyre
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 225/45/17 (5.2.3 (d) (i))
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))

MOT #7

2018-09-03 12:05

MOT test number

610989735561

Result

✓ Passed

- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #6**

2018-09-03 09:13

MOT test number

707804326388

Result

✗ Failed

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Brake pad(s) wear indicator illuminated (1.1.13 (a) (i))**Advice** Offside Rear Nail in tyre**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**Fail** Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #5**

2017-12-04 10:49

MOT test number

647648393833

Result

✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt small split & leaking out grease (2.5.C.1a)**Advice** Nearside Rear no plate light dim/deteriorated**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #4**

2016-11-19 09:40

MOT test number

739748245247

Result

✓ Passed

MOT #3

2016-03-31 13:20

MOT test number

286921580272

Result

✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)



MOT #2	2016-03-31 13:20
MOT test number	957475938799
Result	✗ Failed
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)
Advice	Nearside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #1	2015-04-16 09:23
MOT test number	108046905111
Result	✓ Passed



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-06-28
Current registration	
Plate since	2019-06-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-05-02
Last registration	2023-04-12
Complete history	See info



Registration #1	2012-05-02	19 mi
Registration #2	2015-04-16	59.473 mi
Registration #3	2016-03-31	73.435 mi
Registration #4	2016-03-31	73.435 mi
Registration #5	2016-11-19	82.004 mi
Registration #6	2017-12-04	87.431 mi
Registration #7	2018-09-03	91.781 mi
Registration #8	2018-09-03	91.781 mi
Registration #9	2019-05-20	95.277 mi
Registration #10	2019-05-20	95.277 mi
Registration #11	2019-05-20	95.277 mi
Registration #12	2019-05-20	95.277 mi
Registration #13	2019-05-20	95.277 mi
Registration #14	2019-05-20	95.277 mi
Registration #15	2019-05-20	95.277 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	87%
Pedestrian	74%
Safety systems	86%
Overall rating	88%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1423 mm
Length	4292 mm
Wheel base	2578 mm
Kerb weight	1320 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	CAYCR58709