

Ford



General information

Make	FORD
Model	C-MAX STYLE 100
Colour	Red
Year of manufacture	2007
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	164 g/km
CO2 label	G





Internet history	
Entry 1	
Date	2021-01-29
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-10-08
MOT pass rate	93 %
MOT passed	14
Failed MOT tests	1
Total advice items	21
Total items failed	1

MOT #15	2023-10-09 15:02
MOT test number	329027794605
Result	✓ Passed
Next expiry date	2024-10-08
Advice Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))	

МОТ #14	2022-10-07 08:47
MOT test number	987401202980
Result	✓ Passed

MOT #13	2021-10-08 09:28
MOT test number	995656142883
Result	✓ Passed

MOT #12	2020-10-06 10:51
MOT test number	835157922842
Result	✓ Passed
Advice Nearside Front Lower Suspension arm pin or bush worn but not r	resulting in excessive movement

(rear bush) (5.3.4 (a) (i))

MOT #11	2019-04-05 09:52
MOT test number	275760193972
Result	✓ Passed





MOT #10		2018-04-05 07:56
MOT test	number	772156262176
Result		🗸 Passed
Advice	Nearside Front tyre outer sidewall hard abrasion and rubber decomposing	
Advice	Nearside Front Direction indicator slightly discoloured (1.4.A.2f)	
Advice	Offside Front Direction indicator slightly discoloured (1.4.A.2f)	

MOT #9		2018-04-04 14:43
MOT test	number	342899534177
Result		🗙 Failed
Advice	Offside Front Direction indicator slightly discoloured (1.4.A.2f)	
Advice	Nearside Front Direction indicator slightly discoloured (1.4.A.2f)	
Advice	Nearside Front tyre outer sidewall hard abrasion and rubber decomposing	
Fail O	ffside Front Tyre has ply or cords exposed outer sidewall (4.1.D.1b)	

MOT #8

MOT test number

2017-03-16 16:44

902172210491

Result

✓ Passed

MOT #7	2016-03-17 12:16
MOT test number	646803166004
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Nail in nearside rear tyre	
Advice Engine management light on dash	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	





MOT #6		2015-04-04 11:12
MOT test	number	247344495071
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Child seat fitted not allowing full inspection of adult belt	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #5	2014-04-07 10:39
MOT test number	127337494404
Result	✓ Passed

MOT #4	2013-07-25 09:46
MOT test	number 538046203230
Result	✓ Passed
Advice (2.4.G.2)	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement
Advice (2.4.G.2)	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

MOT #3		2012-08-03 09:57
MOT test	number	848776212289
Result		✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt	
Notice	O/s/r tyre sidewall age cracking.	
Notice	N/s/r tyre sidewall age cracking.	

MOT #2	2011-08-05 11:40
MOT test number	868847611265
Result	✓ Passed





MOT #1	2010-08-10 09:37
MOT test number	284642520287
Result	✓ Passed
Advice Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

√ Taxed	√ МОТ
Tax due: 1 June 2024	Expires: 8 October 2024
Tax status	Valid until 1 June
Days left	33
MOT expiry date	8 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes See in this check if this FORD had different number plates	
Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-10-03
Last registration	2023-10-09
Complete history	See info



Registration #1	2007-10-03	22 mi
Registration #2	2010-08-10	13.106 mi
Registration #3	2011-08-05	17.956 mi
Registration #4	2012-08-03	23.981 mi
Registration #5	2013-07-25	30.115 mi
Registration #6	2014-04-07	34.886 mi
Registration #7	2015-04-04	39.002 mi
Registration #8	2016-03-17	44.417 mi
Registration #9	2017-03-16	51.064 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1372 kg
Max. allowed weight	1855 kg
Additional information	
Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	7J32215