



report date: 2024-03-28

General information

Make	SUZUKI
Model	SWIFT SZ2
Colour	Silver
Year of manufacture	2011
Top speed	103 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	116 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-02-15
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	21
Total items failed	2

MOT #12 2024-02-16 14:05

MOT test number 555525168639

Result ✓ Passed

Next expiry date 2025-02-15

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material from wheel cylinder to hose and from hose to front (1.1.11 (c))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material from hose to wheel cylinder and from hose to front. (1.1.11 (c))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge edge worn (5.2.3 (e))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #11 2023-04-21 14:22

MOT test number 948619556146

Result ✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Front Windscreen wiper blade defective (3.4 (b) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Oil leak, but not excessive oil filter (8.4.1 (a) (i))

**MOT #10** 2023-04-21 10:55**MOT test number** 717033391884**Result** ✗ Failed**Minor** Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Oil leak, but not excessive oil filter (8.4.1 (a) (i))**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Rear Service brake excessively fluctuating (1.2.1 (e))**MOT #9** 2022-04-09 08:19**MOT test number** 341308335552**Result** ✓ Passed**MOT #8** 2021-04-07 09:21**MOT test number** 595703376069**Result** ✓ Passed**MOT #7** 2020-09-18 11:09**MOT test number** 836190980776**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Items removed from driver's view prior to test**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge also cracking/perishing (5.2.3 (e))

**MOT #6** 2019-03-29 09:43**MOT test number** 489992986534**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #5** 2018-03-22 14:01**MOT test number** 270765612079**Result** ✓ Passed**MOT #4** 2017-03-03 12:36**MOT test number** 443294241902**Result** ✓ Passed**MOT #3** 2016-03-04 13:02**MOT test number** 592838747436**Result** ✓ Passed**Advice** Both front tyres low 2.5mm**MOT #2** 2015-03-11 11:25**MOT test number** 178140675414**Result** ✓ Passed**MOT #1** 2014-04-01 14:36**MOT test number** 137111694421**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
15 February 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	15 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-03-23
Last registration	2024-02-16
Complete history	See info



Registration #1	2011-03-23	14 mi
Registration #2	2014-04-01	21.880 mi
Registration #3	2015-03-11	24.180 mi
Registration #4	2016-03-04	26.676 mi
Registration #5	2017-03-03	28.860 mi
Registration #6	2018-03-22	32.065 mi
Registration #7	2019-03-29	39.648 mi
Registration #8	2020-03-29	45.277 mi
Registration #9	2021-03-29	51.277 mi
Registration #10	2022-03-29	57.277 mi
Registration #11	2023-03-29	63.277 mi
Registration #12	2024-02-16	69.277 mi
Registration #13	2024-02-16	69.277 mi
Registration #14	2024-02-16	69.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3850 mm
Wheel base	2430 mm
Kerb weight	1065 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	K12B-1354225