





report date: 2024-03-28

## General information

Make	ТОУОТА
Model	PRIUS VVT-I T SPIRIT
Colour	Grey
Year of manufacture	2007
Top speed	106 mph
0 - 60 mph	10.9 seconds
Gearbox	4 speed CVT

## Engine & fuel consumption

Power	76 BHP	
Max. torque	115 Nm at 4.000 rpm	
Engine capacity	1.497 cc	
Cylinders	4	
Fuel type	Hybrid / Electric	
Consumption city	56.5 mpg	
Consumption extra urban	67.3 mpg	
Consumption combined	65.7 mpg	
CO2 emission	104 g/km	
CO2 label	В	



CarCheck.co.uk page 1/14



## Internet history

#### Entry 1

Date 2021-06-06


Pictures 72

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-06-09
	2021 00 03
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	27
Total items failed	7

MOT #19	2023-05-17 09:57
MOT test number	513458837985
Result	<b>✓</b> Passed
Next expiry date	2024-06-09
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #18	2023-05-17 09:57
MOT test number	687621789273
Result	<b>★</b> Failed
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice Front Brake disc	worn, but not excessively (1.1.14 (a) (i))

MOT #17	2022-06-09 09:38
MOT test number	575054885588
Result	✓ Passed
Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Minor Front Windscreen wiper blade defective (3.4 (b) (i))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)	)

CarCheck.co.uk page 3/14



MOT #12

RJ07PGX report date: 2024-03-28

**MOT #16** 2022-06-09 09:38 **MOT test number** 388953069380 Result × Failed Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii)) Front Windscreen wiper blade defective (3.4 (b) (i)) Minor **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** 

MOT #15	2021-06-01 10:40
MOT test number	660836782453
Result	✓ Passed

MOT #14	2020-06-10 17:04
MOT test number	167050172548
Result	✓ Passed

MOT #13	2019-04-10 15:47
MOT test number	882704500910
Result	<b>✓</b> Passed

1101 #12	2010-03-23 13.14
MOT test number	340324405182
Result	✓ Passed

MOT #11	2017-04-04 08:37
MOT test number	236255296088
Result	✓ Passed

CarCheck.co.uk page 4/14



MOT #10 2017-04-03 11:35

MOT test number 663432379227

Result

× Failed

**Fail** (7.1.2)

Rear Exhaust has a major leak of exhaust gases rear box broken away and not secure on hanger

MOT #9 2016-04-11 14:15

**MOT test number** 975218612869

**Result** 
✓ Passed

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #8 2016-04-11 14:15

**MOT test number** 708407716240

**Result** X Failed

Pass with rectification

Offside Headlamp aim too high (1.8)

**Advice** 

Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Pass with rectification** 

Nearside Headlamp aim too high (1.8)

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2015-03-23 13:45

MOT test number 606962785009

Result

Passed

Notice

Near side rear sill damaged

CarCheck.co.uk page 5/14



MOT test number

477172085092

Result

Fail Offside Headlamp aim too high (1.8)

Notice Wipers poor but clearing screen

Fail Offside Rear coil spring broken (2.4.C.1a)

Notice Near side rear sill damaged

**MOT #5** 2014-04-07 13:20 **MOT** test number 866837194013 ✓ Passed Result **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1) Notice Under-trays fitted obscuring some underside components Notice Rear tyre perished & perished **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Notice Engine covers fitted obscuring some components in the engine bay

MOT #4		2013-04-12 09:29
MOT test	number	469832903147
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Vehicle's internal headlight adjuster altered to recheck lights	

CarCheck.co.uk page 6/14



**Notice** 

RJ07PGX report date: 2024-03-28

MOT #3

MOT test number

128536782077

Result

Notice O/s/r tyre cracked

 MOT #2
 2011-03-28 14:52

 MOT test number
 986327881095

 Result
 ✓ Passed

 MOT #1
 2010-04-28 11:20

 MOT test number
 982398610178

 Result
 ✓ Passed

Some remains from beam pattern coverters on headlamps.

CarCheck.co.uk page 7/14



## Tax & MOT check



Tax status	Valid until 1 December
Days left	217
MOT expiry date	9 June 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	59
Band	В
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-

CarCheck.co.uk page 8/14



#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



## Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full it	
***************************************	
********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	NIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



# Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-04-25
Last registration	2023-05-17
Complete history	See info



Registration #1	2007-04-25	18 mi
Registration #2	2010-04-28	26.631 mi
Registration #3	2011-03-28	33.176 mi
Registration #4	2012-03-26	42.978 mi
Registration #5	2013-04-12	50.546 mi
Registration #6	2014-04-07	59.603 mi
Registration #7	2015-03-23	67.125 mi
Registration #8	2015-03-23	67.125 mi
Registration #9	2016-04-11	78.031 mi
Registration #10	2016-04-11	78.031 mi
Registration #11	2017-04-03	86.497 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		D.777 es
Registration #21		73.777 au

More info >

CarCheck.co.uk page 13/14



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1725 mm
Height	1490 mm
Length	4450 mm
Wheel base	2700 mm
Kerb weight	1325 kg
Max. allowed weight	1725 kg

# Additional information

Fuel tank capacity	45 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pag	e 14/14

Number of axles 2

**Engine number** 1NZU155719