



report date: 2024-03-29

General information

Make	MINI
Model	MINI (R60) COOPER S ALL4
Colour	Red
Year of manufacture	2011
Top speed	134 mph
0 - 60 mph	7.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	46.3 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-07-15
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-13
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	16
Total items failed	19

MOT #17	2023-10-11 17:02
MOT test number	332410521643
Result	✓ Passed
Next expiry date	2024-10-13
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #16	2022-10-14 13:09
MOT test number	833011337113
Result	✓ Passed
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords no cords viable (5.2.3 (d) (i))
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords no cords visible (5.2.3 (d) (i))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords no cords viable (5.2.3 (d) (i))
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #15**

2022-10-13 12:30

**MOT test number**

766632781567

**Result****✗ Failed**

**Fail** Central Front Exhaust Lambda reading after 2nd fast idle outside specified limits see emissions print out. (8.2.1.2 (c))

**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords no cords viable (5.2.3 (d) (i))

**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords no cords visible (5.2.3 (d) (i))

**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords no cords viable (5.2.3 (d) (i))

**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #14**

2022-10-10 16:28

**MOT test number**

331203108117

**Result****✗ Failed**

**Fail** Nearside Front Upper Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))

**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**Fail** Central Front Lower Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))

**Fail** Central Front Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

**Fail** Offside Rear Brake load sensing valve linkage defective and function impaired (1.1.17 (a))

**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**Fail** Offside Front Upper Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))

**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Central Front Lower Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #13**

2021-09-23 12:46

**MOT test number**

878114129571

**Result****✓ Passed**

**MOT #12** 2021-09-21 16:43**MOT test number** 151379254328**Result** ✗ Failed

- Fail** Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Oil leaking continuously from engine posing a serious risk to road safety (8.4.1 (a) (ii))
- Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))
- Fail** Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Hydraulic brake calliper excessively corroded and likely to crack (1.1.16 (d) (ii))
- Fail** Offside Rear Hydraulic brake calliper excessively weakened by corrosion (1.1.16 (d) (i))
- Fail** Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

**MOT #11** 2020-10-14 14:11**MOT test number** 874580411187**Result** ✓ Passed**MOT #10** 2020-10-14 07:54**MOT test number** 364578515224**Result** ✗ Failed

- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #9** 2019-10-22 08:42**MOT test number** 331515746937**Result** ✓ Passed

**MOT #8** 2018-10-31 08:33**MOT test number** 106916328127**Result** ✓ Passed

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #7** 2018-10-30 08:28**MOT test number** 556628194017**Result** ✗ Failed

**Fail** Nearside Front Position lamp not working (4.2.1 (a))

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #6** 2017-10-11 09:22**MOT test number** 510921803425**Result** ✓ Passed**MOT #5** 2017-10-11 07:53**MOT test number** 830467657569**Result** ✓ Passed**MOT #4** 2016-11-02 09:08**MOT test number** 172574030427**Result** ✓ Passed

**Advice** Undertrays fitted obscuring some components

**MOT #3** 2016-03-25 14:47**MOT test number** 831845035955**Result** ✓ Passed



MOT #2	2015-03-06 07:59
MOT test number	568095765050
Result	✓ Passed

MOT #1	2014-03-07 13:21
MOT test number	567636664072
Result	✓ Passed
<div>Notice Engine covers fitted obscuring some components in the engine bay</div> <div>Notice Under-trays fitted obscuring some underside components</div>	



Tax & MOT check

X

Untaxed

Tax expired:  
20 February 2024

✓

MOT

Expires:  
13 October 2024

Tax status	Expired at 20 February 2024
Days left	70 days too late
MOT expiry date	13 October 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-03-01
Last registration	2023-10-11
Complete history	<a href="#">See info</a>



Registration #1	2011-03-01	22 mi
Registration #2	2014-03-07	24.706 mi
Registration #3	2015-03-06	34.829 mi
Registration #4	2016-03-25	45.531 mi
Registration #5	2016-11-02	48.048 mi
Registration #6	2017-10-11	54.535 mi
Registration #7	2017-10-11	54.535 mi
Registration #8	2018-10-30	60.168 mi
Registration #9	2018-10-31	60.168 mi
Registration #10	2019-10-22	64.342 mi
Registration #11	2019-10-22	64.342 mi
Registration #12	2019-10-22	64.342 mi
Registration #13	2019-10-22	64.342 mi
Registration #14	2019-10-22	64.342 mi
Registration #15	2019-10-22	64.342 mi
Registration #16	2019-10-22	64.342 mi
Registration #17	2019-10-22	64.342 mi
Registration #18	2019-10-22	64.342 mi
Registration #19	2019-10-22	64.342 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1390 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	B228J007