





### General information

Make	HONDA
Model	ACCORD VTEC EX
Colour	Silver
Year of manufacture	2007
Top speed	134 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	153 BHP
Max. torque	190 Nm at 4.500 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.2 mpg
Consumption extra urban	44.8 mpg
Consumption combined	33.6 mpg
CO2 emission	200 g/km
CO2 label	J







# Internet history

Entry 1

Date Pictures 2021-07-20

57

Listing price

View report









source: autotrader.co.uk



# MOT history

MOT expiry date	2025-05-18
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	24
Total items failed	7

MOT #19		2024-04-22 11:24
MOT test	: number	640175278826
Result		✓ Passed
Next exp	iry date	2025-05-18
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both sides	(1.1.14 (a) (ii))
Advice	Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Advice Offside Rear Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Advice Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	





MOT #18		2024-04-22 11:24
MOT test number		168454673974
Result		🗙 Failed
Advice Offside Rear Ar	nti-roll bar pin or bush worn but not resulting in ex	cessive movement (5.3.4 (a) (i))
Advice Nearside Rear	Tyre slightly damaged/cracking or perishing (5.2.3	3 (d) (ii))
Minor Windscreen dan	naged but not adversely affecting driver's view (3	.2 (a) (i))
Pass with rectification	Nearside Stop lamp(s) not working (4.3.1 (a) (i	i))
Pass with rectification	Offside Front Position lamp not working (4.2.1	(a) (ii))
Advice Nearside Front	Anti-roll bar linkage ball joint has slight play (5.3.	4 (a) (i))
Advice Offside Rear Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))		
Advice Front Brake dis	c worn, pitted or scored, but not seriously weaker	ned both sides (1.1.14 (a) (ii))
<b>Pass with rectification</b> (ii))	Nearside Windscreen wiper does not clear the	windscreen effectively (3.4 (b)

MOT #17	2023-05-19 11:	48
MOT test	number 9090315945	36
Result	✓ Pass	ed
Advice Front Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))		
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

МОТ #16	2022-07-13 09:47
MOT test number	803046538485
Result	✓ Passed
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	





MOT #15	2021-07-05 10:08
MOT test number	728328897154
Result	✓ Passed
MOT #14	2020-06-17 07:56
MOT test number	588048034363
Result	✓ Passed
MOT #13	2019-06-26 08:53
MOT test number	290886079056
Result	✓ Passed
MOT #12	2019-06-25 15:08
MOT test number	273484093901
Result	🗙 Failed
Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #11	2018-06-20 14:10
MOT test number	954697583473
Result	✓ Passed
MOT #10	2018-06-20 14:10
MOT test number	692883393863
Result	🗙 Failed

Pass with rectification

Offside Headlamp light intensity severely reduced (4.1.4 (a))





MOT #9	2017-	-06-15 16:44
MOT test number	231	1463455791
Result		✓ Passed
Advice Nearside Windso	screen has damage to an area less than a 40mm circle outside zone 'A' (	8.3.1d)
MOT #8	2017-	-06-15 16:44
MOT #8 MOT test number		-06-15 16:44 9091059888
MOT test number		9091059888

MOT #7		2016-06-16 12:06
MOT test	number	158496915433
Result		✓ Passed
Advice	Nearside Windscreen has damage to an area less than a 40mm circle ou	tside zone 'A' (8.3.1d)

МОТ #6	2015-06-17 10:14
MOT test number	109838265145
Result	✓ Passed

MOT #5	2014-06-17 14:47
MOT test number	149778064147
Result	✓ Passed
Notice Nail in nearside rear tyre	

MOT #4		2013-06-17 08:58
MOT test i	number	405988763147
Result		✓ Passed
Advice	Nearside Windscreen has damage to an area less than a 40mm circle outsi	de zone 'A' (8.3.1d)





MOT #3		2012-06-19 15:34
MOT test	number	938421572197
Result		✓ Passed
Advice	Nearside Windscreen has damage to an area less than a 40mm circ	le outside zone 'A' (8.3.1d)
MOT #2		2011-06-27 16:22
MOT test	number	275198071127
Result		✓ Passed
Advice	Nearside Windscreen has damage to an area less than a 40mm circ	le outside zone 'A' (8.3.1d)
MOT #1		2010-06-23 16:45

MOT test	number	
----------	--------	--

Result

🗸 Passed



Tax & MOT check

<b>Taxed</b> <b>Tax due:</b> 1 August 2024	<b>C</b> MOT Expires: 18 May 2025
Tax status	Valid until 1 August
Days left	95
MOT expiry date	18 May 2025
Full MOT history	See MOT history

# Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





### Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		Lawer
Туре	(*******	
Damage 2		AMPLE
Damage 2		E CONTRACTOR
Date		
Category		AMP
Туре		

#### Extra HONDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





### Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
************	
********	
*******	
************	
********	
	More info >
Plate changes	
See in this check if this HONDA had different number plate	S.
Number of plates	9
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





### Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-07-13
Last registration	2024-04-22
Complete history	See info



Registration #1	2007-07-13	10 mi
Registration #2	2010-06-23	33.343 mi
Registration #3	2011-06-27	45.295 mi
Registration #4	2012-06-19	57.491 mi
Registration #5	2013-06-17	68.971 mi
Registration #6	2014-06-17	83.366 mi
Registration #7	2015-06-17	93.723 mi
Registration #8	2016-06-16	104.344 mi
Registration #9	2017-06-15	114.417 mi
Registration #10	2017-06-15	114.417 mi
Registration #11	2018-06-20	124.606 mi
Registration #12		11.777 esi
Registration #13		11.777 esi
Registration #14		11.777 est
Registration #15		11.777 esi
Registration #16		11.777 est
Registration #17		11.222 esi
Registration #18		11.777 est
Registration #19		11.117 esi
Registration #20		11.117 est
Registration #21		11.777 esi

More info >





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1760 mm
Height	1445 mm
Length	4665 mm
Wheel base	2670 mm
Max. allowed weight	1920 kg
Additional information	
Additional information Fuel tank capacity	65 l
	65 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 4