



General information

Make	MINI
Model	MINI COOPER SD CLUBMAN
Colour	Blue
Year of manufacture	2011
Top speed	134 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-13
Pictures	27
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-19
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	18
Total items failed	6

MOT #16	2023-09-20 13:57
MOT test number	591808163588
Result	✓ Passed
Next expiry date	2024-09-19

MOT #15	2022-07-14 08:30
MOT test number	792245623208
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Play in steering rack inner joint(s)
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake lining(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Play in steering rack inner joint(s)

**MOT #14** 2022-07-13 14:21**MOT test number** 251930964959**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Front Brake lining(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Play in steering rack inner joint(s)**MOT #13** 2021-06-16 16:15**MOT test number** 906859381494**Result** ✓ Passed**MOT #12** 2021-06-16 11:37**MOT test number** 916685786433**Result** ✗ Failed**Fail** Nearside Front Suspension component ball joint excessively worn (5.3.4 (a) (i))**MOT #11** 2020-09-24 12:12**MOT test number** 546014747400**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #10** 2019-09-27 15:11**MOT test number** 424107668952**Result** ✓ Passed

**MOT #9** 2019-09-27 08:52**MOT test number** 269890903295**Result** ✗ Failed**Fail** Offside Rear Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #8** 2018-09-26 10:15**MOT test number** 196584988730**Result** ✓ Passed**MOT #7** 2017-09-28 11:27**MOT test number** 195603502267**Result** ✓ Passed**Advice** Engine covers and under trays fitted obscuring some components**MOT #6** 2017-09-28 09:12**MOT test number** 169412885695**Result** ✗ Failed**Fail** Offside Front Shock absorber has a serious fluid leak (2.7.3)**Advice** Engine covers and under trays fitted obscuring some components**MOT #5** 2016-09-29 08:33**MOT test number** 270047327468**Result** ✓ Passed**MOT #4** 2015-10-02 10:49**MOT test number** 707877139805**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

**MOT #3** 2015-10-02 08:51**MOT test number** 643448479780**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #2** 2014-10-07 10:01**MOT test number** 658350784231**Result** ✓ Passed**MOT #1** 2014-10-06 16:30**MOT test number** 986409974215**Result** ✗ Failed**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Notice** Rear right tyre worn low inner edge



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✓  
**MOT**  
  
Expires:  
19 September 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	19 September 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-10-29
Last registration	2023-09-20
Complete history	<a href="#">See info</a>



Registration #1	2011-10-29	17 mi
Registration #2	2014-10-06	40.729 mi
Registration #3	2014-10-07	40.739 mi
Registration #4	2015-10-02	53.187 mi
Registration #5	2015-10-02	53.187 mi
Registration #6	2016-09-29	64.573 mi
Registration #7	2017-09-28	76.039 mi
Registration #8	2017-09-28	76.039 mi
Registration #9	2018-09-26	84.997 mi
Registration #10	2019-09-20	95.377 mi
Registration #11	2019-09-20	95.377 mi
Registration #12	2019-09-20	95.377 mi
Registration #13	2019-09-20	95.377 mi
Registration #14	2019-09-20	95.377 mi
Registration #15	2019-09-20	95.377 mi
Registration #16	2019-09-20	95.377 mi
Registration #17	2019-09-20	95.377 mi
Registration #18	2019-09-20	95.377 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1432 mm
Length	3961 mm
Wheel base	2547 mm
Kerb weight	1235 kg
Max. allowed weight	1735 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	71657773