



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I30 CRDI SE NAV BLUE DRIVE
Colour	Black
Year of manufacture	2017
Top speed	115 mph
0 - 60 mph	11.2 seconds
Gearbox	7 speed Semi-Automatic

Engine & fuel consumption

Power	109 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	76.4 mpg
Consumption combined	72.4 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 2

Date	2023-12-19
Pictures	50
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-06-18
Pictures	1
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-06-13
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	11
Total items failed	0

## MOT #4 2023-06-14 14:32

MOT test number 534812799024

Result ✓ Passed

Next expiry date 2024-06-13

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

## MOT #3 2023-06-13 08:22

MOT test number 719780196435

Result ✗ Failed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Offside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



MOT #2	2022-06-07 15:59
MOT test number	750945085078
Result	✓ Passed
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Minor	Offside Rear Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #1	2021-06-14 09:37
MOT test number	178846406943
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
13 June 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	13 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>First licence fee (12 months)</b>	£ 185,00,-
<b>First licence fee diesel non RDE2 tested (12 months)</b>	£ 210,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>EA67CYV</b>
Plate since	2019-03-29
Current registration	<b>EA67CYV</b>
Plate since	2019-03-29

More info >





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-09-29
Last registration	2023-06-14
Complete history	<a href="#">See info</a>



Registration #1	2017-09-29	25 mi
Registration #2	2021-06-14	31.797 mi
Registration #3	2022-06-07	38.437 mi
Registration #4		
Registration #5		
Registration #6		
Registration #7		

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	64%
Safety systems	68%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1780 mm
Height	1470 mm
Length	4300 mm
Wheel base	2650 mm
Kerb weight	1456 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D4FBHZ172629