





report date: 2024-03-28

## General information

| Make                | HYUNDAI        |
|---------------------|----------------|
| Model               | KONA PREMIUM   |
| Colour              | Grey           |
| Year of manufacture | 2018           |
| Top speed           | 112 mph        |
| 0 - 60 mph          | 12.0 seconds   |
| Gearbox             | 6 speed Manual |

## Engine & fuel consumption

| Power                   | 118 BHP             |
|-------------------------|---------------------|
| Max. torque             | 171 Nm at 4.000 rpm |
| Engine capacity         | 998 cc              |
| Cylinders               | 3                   |
| Fuel type               | Petrol              |
| Consumption city        | 44.8 mpg            |
| Consumption extra urban | 56.5 mpg            |
| Consumption combined    | 52.3 mpg            |
| CO2 emission            | 127 g/km            |
| CO2 label               | D                   |



CarCheck.co.uk page 1/10



## Internet history

| _ | _ | _ |    | _ | - |
|---|---|---|----|---|---|
| 드 | n | C | ľν | 7 | 1 |

| Lifety 1      |             |
|---------------|-------------|
| Date          | 2022-07-28  |
| Pictures      | 0           |
| Listing price | View report |

source: cargurus.co.uk

CarCheck.co.uk page 2/10



MOT history

| MOT expiry date    | 2024-07-24 |
|--------------------|------------|
| MOT pass rate      | 100 %      |
| MOT passed         | 3          |
| Failed MOT tests   | 0          |
| Total advice items | 5          |
| Total items failed | 0          |

| MOT #3    |  | 2023-07-10 09:24 |
|-----------|--|------------------|
| MOT test  | number   | 238553847809     |
| Result    |  | ✓ Passed         |
| Next expi | ry date  | 2024-07-24       |
| Advice    | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))       |                  |
| Advice    | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))  |                  |
| Advice    | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))      |                  |
| Advice    | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |                  |

| MOT #2  | 2022-07-22 11:50 |
|---|------------------|
| MOT test number   | 179279689974     |
| Result  | ✓ Passed         |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |

| MOT #1          | 2021-07-20 11:00 |
|-----------------|------------------|
| MOT test number | 932981946366     |
| Result          | ✓ Passed         |

CarCheck.co.uk page 3/10



#### Tax & MOT check



| Tax status       | Valid until 1 August |
|------------------|----------------------|
| Days left        | 93                   |
| MOT expiry date  | 24 July 2024         |
| Full MOT history | See MOT history      |

#### Tax calculation

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

| e when misterly   |             |
|---|-------------|
| For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full is |             |
| *********   |             |
| ***************************************   |             |
| *************   |             |
|   |             |
| ***************************************   |             |
|   |             |
| ***************************************   |             |
|   | More info > |
| Plate changes   |             |
| See in this check if this HYUNDAI had different number plates.  |             |
| Number of plates  |             |
| Current registration  | IK SIN      |
| Plate since   |             |
| Current registration  | NK NK       |
| Plate since   |             |
|   | More info > |
|   |             |

CarCheck.co.uk page 7/10



#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |

**Contact info** 

More info >

CarCheck.co.uk page 8/10



# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 5          |
| First mileage registration | 2018-07-25 |
| Last registration          | 2023-07-10 |
| Complete history           | See info   |



| Registration #1 | 2018-07-25 | 8 mi      |
|-----------------|------------|-----------|
| Registration #2 | 2021-07-20 | 28.400 mi |
| Registration #3 | 2022-07-22 | 39.975 mi |
| Registration #4 |            | 77,777 44 |
| Registration #5 |            | 11.777 es |

More info >

CarCheck.co.uk page 9/10




## Car features

| 50225 | Air conditionin |
|-------|-----------------|
| 50295 |                 |
| 50482 |                 |
| 50501 |                 |
| 50566 |                 |
| 50567 |                 |
| 50569 |                 |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 87%             |
| Children       | 85%             |
| Pedestrian     | 62%             |
| Safety systems | 60%             |
| Overall rating | 76%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 1800 mm |
|---------------------|---------|
| Height              | 1565 mm |
| Length              | 4165 mm |
| Wheel base          | 2600 mm |
| Kerb weight         | 1350 kg |
| Max. allowed weight | 1775 kg |

# Additional information

| Fuel tank capacity                | 50 I             |
|-----------------------------------|------------------|
| Fuel delivery                     | Direct Injection |
| Number of doors                   | 5                |
| Number of seats<br>CarCheck.co.uk | 5 page 10,       |

Number of axles 2

**Engine number** G3LCJU023329