





### General information

Make	MINI
Model	COUNTRYMAN COOPER D
Colour	Red
Year of manufacture	2013
Top speed	116 mph
0 - 60 mph	10.8 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 2.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	С







Internet history	
Entry 1	
Date	2021-02-02
Pictures	1
Listing price	View report



source: autoonline.co.uk



### MOT history

MOT expiry date	2024-11-29
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	7
Total items failed	3

МОТ #9	2023-11-28 10:56
MOT test number	933705711938
Result	✓ Passed
Next expiry date	2024-11-29

MOT #8		2022-11-17 10:55
MOT test	number	992455564360
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2021-11-19 15:53
MOT test number	676436021647
Result	✓ Passed

MOT #6	2020-11-30 16:11
MOT test number	565500508039
Result	✓ Passed

MOT #5	2019-11-18 12:13
MOT test number	375951980463
Result	✓ Passed





MOT #4	2019-11-15 13:20
MOT test number	411654952492
Result	🗙 Failed
<b>Fail</b> Nearside Front Upper Macpherson strut mounting damaged and seriously weake (5.3.3 (b) (i))	ned top mount split
Fail Central Rear Brake pad(s) less than 1.5 mm thick Rear brake pads are on 1 mm	(1.1.13 (a) (ii))
<b>Fail</b> Offside Front Upper Macpherson strut mounting corroded and seriously weakene (5.3.3 (b) (i))	ed top mount split
MOT #3	2018-11-01 10:27

MOT test number	327294359969
Result	✓ Passed
Advice Nearside Front Upper Macpherson strut mounting damaged but not seriously weat to crack (5.3.3 (b) (i))	kened Starting
Advice Offside Front Upper Macpherson strut mounting damaged but not seriously weakened Starting to crack (5.3.3 (b) (i))	
Advice Nearside Rear Outer Brake pad(s) wearing thin 3mm (1.1.13 (a) (ii))	

MOT #2	2017-11-06 15:28
MOT test number	193896820536
Result	✓ Passed
<b>Advice</b> Nearside Front Front suspension has slight deterioration of the bonding be flexible material of an upper support bearing (2.5.B.3a)	etween metal and
<b>Advice</b> Offside Front Front suspension has slight deterioration of the bonding between material of an upper support bearing (2.5.B.3a)	ween metal and flexible

MOT #1	2016-11-15 12:06
MOT test number	452331621452
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 February 2025	✓ MOT Expires: 29 November 2024
Tax status	Valid until 1 February
Days left	279
MOT expiry date	29 November 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	K K K
Damage 2	AMPL
	F Store
Date	 1. F
Category	 ant
Туре	

#### Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	
************	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	





#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





## Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-11-22
Last registration	2023-11-28
Complete history	See info



Registration #1	2013-11-22	7 mi
Registration #2	2016-11-15	21.682 mi
Registration #3	2017-11-06	28.972 mi
Registration #4	2018-11-01	34.050 mi
Registration #5	2019-11-15	41.495 mi
Registration #6	2019-11-18	41.496 mi
Registration #7		11.777 mi
Registration #8		11.777 est
Registration #8 Registration #9		11.777 es
		11.227 est 21.227 est 21.227 est

More info  $\rightarrow$ 





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight	
Width	1996 mm
Height	1518 mm
Length	4109 mm
Wheel base	2596 mm
Kerb weight	1300 kg
Max. allowed weight	1770 kg
Additional information	
Fuel tank capacity	47
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 11/11

**Engine number** 

72058567