





### General information

| Make                | VAUXHALL                    |
|---------------------|-----------------------------|
| Model               | CORSA SRI VX-LINE NAV BLACK |
| Colour              | White                       |
| Year of manufacture | 2018                        |
| Top speed           | 109 mph                     |
| 0 - 60 mph          | 13.2 seconds                |
| Gearbox             | 5 speed Manual              |

### Engine & fuel consumption

| Power                   | 89 BHP              |
|-------------------------|---------------------|
| Max. torque             | 130 Nm at 4.000 rpm |
| Engine capacity         | 1.398 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 39.2 mpg            |
| Consumption extra urban | 58.9 mpg            |
| Consumption combined    | 43.5 mpg            |
| CO2 emission            | 130 g/km            |
| CO2 label               | D                   |







# Internet history

Entry 1

Date Pictures 2021-12-11

12

Listing price

View report



source: cargurus.co.uk



# MOT history

| MOT expiry date    | 2024-10-18 |
|--------------------|------------|
| MOT pass rate      | 75 %       |
| MOT passed         | 3          |
| Failed MOT tests   | 1          |
| Total advice items | 3          |
| Total items failed | 1          |

| MOT #4           | 2023-10-16 09:41 |
|------------------|------------------|
| MOT test number  | 869259189843     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-10-18       |

| MOT #3   | 2022-10-03 15:38 |
|--|------------------|
| MOT test number  | 300600865857     |
| Result   | ✓ Passed         |
| Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b)) |                  |

| MOT #2   | 2022-10-03 08:14                |
|--|---------------------------------|
| MOT test number  | 300404707304                    |
| Result   | 🗙 Failed                        |
| <b>Minor</b> Offside Front Outer Track rod end ball joint dust cover damaged or de ingress of dirt (2.1.3 (g) (i)) | eteriorated, but preventing the |
| Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))   |                                 |
| FailOffside Front Upper Macpherson strut top bush or bearing has excessive(i))                                     | e wear or free play (5.3.4 (a)  |

| MOT #1          | 2021-10-01 09:26 |
|-----------------|------------------|
| MOT test number | 134630986354     |
| Result          | ✓ Passed         |



Tax & MOT check

| ✓<br>Taxed<br>Tax due:<br>1 January 2025 | ✓<br>MOT<br>Expires:<br>18 October 2024 |
|--|---|
| Tax status                               | Valid until 1 January                   |
| Days left                                | 248                                     |
| MOT expiry date                          | 18 October 2024                         |
| Full MOT history                         | See MOT history                         |

# Tax calculation

| Vehicle class                 | 48         |
|-------------------------------|------------|
| Band                          | G          |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months)     | £ 180,00,- |
| Standard rate (6 months)      | £ 99,00,-  |
| Premium rate (12 months)      | £ 570,00,- |
| Premium rate (6 months)       | £ 313,50,- |





### Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |       |
|----------|-------|
| Date     | FET A |
| Category | L AMP |
| Туре     |       |
| Damage 2 | AMPLE |
| Date     | 4     |
| Category | AMPL  |
| Туре     |       |

#### Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4.00.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 10.200 |





### Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| NUMBER OF TAXABLE PARTY |             |
|--|-------------|
| ********   |             |
| ********   |             |
|  |             |
|  |             |
| ***********  |             |
| ********   |             |
|  |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this VAUXHALL had different number plates.  |             |
| Number of plates   | ,           |
| Current registration   |             |
| Plate since  |             |
| Current registration   |             |
| Plate since  |             |
|  | More info > |





### Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.


| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |





# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 6          |
| First mileage registration | 2018-10-19 |
| Last registration          | 2023-10-16 |
| Complete history           | See info   |



| Registration #1 | 2018-10-19 | 19 mi      |
|-----------------|------------|------------|
| Registration #2 | 2021-10-01 | 15.938 mi  |
| Registration #3 |            | 11.777 mi  |
| Registration #4 |            | 11.777 esi |
| Registration #5 |            | 11.777 mi  |
| Registration #6 |            | 11.117 esi |





# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 79%             |
| Children       | 77%             |
| Pedestrian     | 71%             |
| Safety systems | 56%             |
| Overall rating | 72%             |
| Video          | see crash video |



| Dimensions & weight    |                            |
|------------------------|----------------------------|
| Width                  | 1746 mm                    |
| Height                 | 1481 mm                    |
| Length                 | 4021 mm                    |
| Wheel base             | 2510 mm                    |
| Kerb weight            | 1088 kg                    |
| Max. allowed weight    | 1630 kg                    |
| Additional information |                            |
| Fuel tank capacity     | 45 I                       |
| Fuel delivery          |                            |
|                        | Multi-Point Injection      |
| Number of doors        | Multi-Point Injection<br>5 |
|                        | -                          |
| Number of doors        | 5                          |