



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	207 HDI S
Colour	Blue
Year of manufacture	2009
Top speed	103 mph
0 - 60 mph	14.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	76.4 mpg
Consumption combined	64.2 mpg
CO2 emission	117 g/km
CO2 label	C







Internet history

Entry 1

Date	2021-06-08
Pictures	84
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-29
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	47
Total items failed	16

MOT #18	2023-08-29 14:52
MOT test number	568629924843
Result	✓ Passed
Next expiry date	2024-08-29
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #17	2023-08-29 14:51
MOT test number	860337856578
Result	✗ Failed
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Pass with rectification	Windscreen washer not working (3.5 (a))

**MOT #16** 2022-08-30 15:10**MOT test number** 599043883139**Result** ✓ Passed

- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #15** 2021-08-27 16:48**MOT test number** 392184347533**Result** ✓ Passed**MOT #14** 2020-11-26 13:05**MOT test number** 592901551294**Result** ✓ Passed

- Advice** Corrosion on underside inc suspension/ sub frame and rear axel
- Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn both n/s/r and o/s/r (5.1.2 (b) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view chip (3.2 (a) (i))
- Advice** Front and rear heat shields missing
- Advice** Rear Brake hose has slight corrosion to ferrule both n/s/r and o/s/r (1.1.12 (f) (i))
- Advice** Front exhaust bracket broken but has temp repair
- Advice** Rear Tyre slightly damaged/cracking or perishing both n/s/r and o/s/r starting to crack (5.2.3 (d) (ii))

**MOT #13**

2020-11-10 09:55

**MOT test number**

995494216580

**Result****✗ Failed****Fail** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))**Advice** Handbrake has free play when operated due to fault with nearside rear brake**Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Advice** All tyres cracking in tread**Advice** Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**MOT #12**

2019-11-15 16:00

**MOT test number**

961906967155

**Result****✓ Passed****Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #11**

2019-11-15 13:37

**MOT test number**

865932681732

**Result**

✗ Failed

**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #10**

2018-11-14 09:28

**MOT test number**

285699533073

**Result**

✓ Passed

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #9**

2017-11-15 10:17

**MOT test number**

595781691089

**Result**

✓ Passed

**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #8**

2016-12-05 13:57

**MOT test number**

106604459788

**Result**

✓ Passed

**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #7** 2016-12-05 09:35**MOT test number** 702268601901**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Nearside Rear Mechanical brake component has restricted free movement (3.5.1k)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Rear Mechanical brake component has restricted free movement (3.5.1k)**MOT #6** 2015-11-05 10:59**MOT test number** 580158572014**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Nearside Front wiper blade deteriorated**MOT #5** 2015-11-03 10:25**MOT test number** 183081176748**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Nearside Rear nail in tyre**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front wiper blade deteriorated

**MOT #4** 2014-11-06 12:34**MOT test number** 406320814499**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #3** 2014-11-06 11:32**MOT test number** 445500514426**Result** ✗ Failed**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Centre Front Exhaust system not adequately supported (7.1.1)**Fail** Centre Rear Exhaust system not adequately supported (7.1.1)**MOT #2** 2013-11-07 10:19**MOT test number** 138151613364**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #1** 2012-11-15 15:35**MOT test number** 495650622379**Result** ✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
29 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	29 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>YY59KBX</b>
Plate since	2019-03-29
Current registration	<b>YY59KBX</b>
Plate since	2019-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-11-26
Last registration	2023-08-29
Complete history	<a href="#">See info</a>



Registration #1	2009-11-26	10 mi
Registration #2	2012-11-15	19.339 mi
Registration #3	2013-11-07	23.850 mi
Registration #4	2014-11-06	31.285 mi
Registration #5	2014-11-06	31.285 mi
Registration #6	2015-11-03	39.585 mi
Registration #7	2015-11-05	39.651 mi
Registration #8	2016-12-05	47.821 mi
Registration #9	2016-12-05	47.821 mi
Registration #10	2017-11-15	50.143 mi
Registration #11	2018-01-01	51.217 mi
Registration #12	2018-01-01	51.217 mi
Registration #13	2018-01-01	51.217 mi
Registration #14	2018-01-01	51.217 mi
Registration #15	2018-01-01	51.217 mi
Registration #16	2018-01-01	51.217 mi
Registration #17	2018-01-01	51.217 mi
Registration #18	2018-01-01	51.217 mi
Registration #19	2018-01-01	51.217 mi
Registration #20	2018-01-01	51.217 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1261 kg
Max. allowed weight	1660 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	FDAX2402683