






General information

MakePEUGEOTModel107 MILLESIMColourBlueYear of manufacture2010Top speed100 mph0 - 60 mph14.2 secondsGearbox5 speed Manual		
ColourBlueYear of manufacture2010Top speed100 mph0 - 60 mph14.2 seconds	Make	PEUGEOT
Year of manufacture 2010 Top speed 100 mph 0 - 60 mph 14.2 seconds	Model	107 MILLESIM
Top speed 100 mph 0 - 60 mph 14.2 seconds	Colour	Blue
0 - 60 mph 14.2 seconds	Year of manufacture	2010
	Top speed	100 mph
Gearbox 5 speed Manual	0 - 60 mph	14.2 seconds
	Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	106 g/km
CO2 label	В







Internet history

Entry	1

Date Pictures 2021-06-16

17

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-03
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	24
Total items failed	6

MOT #14		2023-07-04 06:49
MOT test	number	616741618123
Result		✓ Passed
Next exp	iry date	2024-07-03
Minor	Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (o) (i))
Advice	Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))	
Minor	Obligatory mirror slightly damaged Interior mirror deteriorated (3.3 (b) (i))	
Advice	Damage to near side front bumper and surrounding area radiator hose fowling o	on engine





MOT #13		2023-07-03 10:36
MOT test	number	166366645410
Result		🗙 Failed
Minor	Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b)	(i))
MAJOR	Horn not working (7.7 (a))	
MAJOR	Rear fog lamp not working (4.5.1 (a) (ii))	
Advice	Damage to near side front bumper and surrounding area radiator hose fowling on	engine
MAJOR	Nearside Rear Service brake excessively binding (1.2.1 (f))	
MAJOR	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Minor	Obligatory mirror slightly damaged Interior mirror deteriorated (3.3 (b) (i))	
MAJOR	Rear fog lamp switch not operating in accordance with the requirements (4.5.3 (a))
MAJOR	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Advice	Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))	

MOT #12		2022-06-21 07:50
MOT test	number	878687820169
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Front Tyre slightly damaged/cracking or perishing side wall (5.2.3 (d) (ii))))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #11	2021-06-09 11:55
MOT test number	656297657038
Result	✓ Passed





MOT #10		2020-06-16 10:36
MOT test	number	887545638264
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice (5.3.4 (a)	Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in exces (i))	ssive movement
Advice	Nearside Front Tyre slightly damaged/cracking or perishing sidewall (5.2.3 (d)	(ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice (a) (i))	Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excess	ive movement (5.3.4

МОТ #9	2019-06-10 14:57
MOT test number	375177640903
Result	Passed
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))	

MOT #8	2018-06-12 13:52
MOT test number	769900717743
Result	✓ Passed

MOT #7	2018-05-04 12:48
MOT test number	343304078716
Result	🗙 Failed
Fail Offside Indicator tell tale inoperative (1.4.A.2a)	
Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords sidewall (4.1.D.1a)	

MOT #6	2017-04-28 08:19
MOT test number	477345492584
Result	🗸 Passed
Advice Rear o/s exhaust hanger deteriorating	





MOT #5	2016-05-05 08:24
MOT test number	661724316185
Result	✓ Passed
MOT #4	2015-05-08 11:25
MOT test number	186578525159
Result	✓ Passed
MOT #3	2014-05-12 10:18
MOT test number	626312234162
Result	✓ Passed
NOT #2	
MOT #2	2013-05-10 16:38
MOT test number	889160633192
Result	✓ Passed
MOT #1	2013-05-10 09:13
MOT test number	916650733194
Result	🗙 Failed
Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)	
Fail Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)	
Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)	
Fail Offside Rear Tyre has ply or cords exposed (4.1.D.1b)	



Tax & MOT check

✓ Taxed Tax due: 1 July 2024	✓ MOT Expires: 3 July 2024
Tax status	Valid until 1 July
Days left	62
MOT expiry date	3 July 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. DEM PE
Туре	
Damage 2	AMPL
Date	ALL I
Category	ant.
Туре	

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-05-11
Last registration	2023-07-04
Complete history	See info



Registration #1	2010-05-11	13 mi
Registration #2	2013-05-10	16.641 mi
Registration #3	2013-05-10	16.641 mi
Registration #4	2014-05-12	20.313 mi
Registration #5	2015-05-08	23.406 mi
Registration #6	2016-05-05	25.799 mi
Registration #7	2017-04-28	28.048 mi
Registration #8	2018-05-04	31.024 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
\$0566	
50567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	865 kg
Max. allowed weight	1180 kg
Additional information	
Fuel tank capacity	35
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13