





report date: 2024-03-28

General information

| Make | HYUNDAI |
|---------------------|----------------------------------|
| Model | SANTA FE CRDI PREMIUM BLUE DRIVE |
| Colour | White |
| Year of manufacture | 2016 |
| Top speed | 118 mph |
| 0 - 60 mph | 9.0 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 194 BHP |
|-------------------------|---------------------|
| Max. torque | 422 Nm at 2.500 rpm |
| Engine capacity | 2.199 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 37.7 mpg |
| Consumption extra urban | 54.3 mpg |
| Consumption combined | 46.3 mpg |
| CO2 emission | 159 g/km |
| CO2 label | G |



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-07-17

Pictures 8

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2024-07-27 |
|--------------------|------------|
| MOT pass rate | 83 % |
| MOT passed | 5 |
| Failed MOT tests | 1 |
| Total advice items | 3 |
| Total items failed | 1 |

| MOT #6 | 2023-07-28 12:54 |
|---|------------------|
| MOT test number | 176054385984 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-27 |
| Advice Oil leak, but not excessive transfer box (8.4.1 (a) (i)) | |

| MOT #5 | 2023-07-20 11:20 |
|---|------------------|
| MOT test number | 557931334299 |
| Result | X Failed |
| Advice Oil leak, but not excessive transfer box (8.4.1 (a) (i)) Fail Nearside Side repeater not working (4.4.1 (a) (ii)) | |

| MOT #4 | 2022-07-13 11:53 |
|---|------------------|
| MOT test number | 420161747552 |
| Result | ✓ Passed |
| Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| MOT #3 | 2021-07-21 15:01 |
|-----------------|------------------|
| MOT test number | 698112703649 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



Result

EY66OYL report date: 2024-03-28

✓ Passed

| MOT #2 | 2020-10-01 15:23 |
|-----------------|------------------|
| MOT test number | 115841525363 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2019-08-30 08:53 |
| MOT test number | 480835783060 |

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 August |
|------------------|----------------------|
| Days left | 94 |
| MOT expiry date | 27 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| e when miscory | |
|--|-------------|
| For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations. | |
| | |
| | |
| | |
| | |
| ******* | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this HYUNDAI had different number plates. | |
| Number of plates | , |
| Current registration | NK SIN |
| Plate since | |
| Current registration | NK. |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 8/11



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2016-09-07 |
| Last registration | 2023-07-28 |
| Complete history | See info |



| Registration #1 | 2016-09-07 | 8 mi |
|-----------------|------------|-----------|
| Registration #2 | 2019-08-30 | 26.527 mi |
| Registration #3 | 2020-10-01 | 31.720 mi |
| Registration #4 | | 11.777 es |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 71.777 es |

More info >

CarCheck.co.uk page 10/11



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| S0501 | |
| S0566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 96% |
| Children | 89% |
| Pedestrian | 71% |
| Safety systems | 86% |
| Overall rating | 89% |
| Video | see crash video |



Dimensions & weight

| Width | 1880 mm |
|---------------------|---------|
| Height | 1690 mm |
| Length | 4690 mm |
| Wheel base | 2700 mm |
| Kerb weight | 1939 kg |
| Max. allowed weight | 2510 kg |

Additional information

| Fuel tank capacity | 64 I | |
|-----------------------------------|------------------|-------|
| Fuel delivery | Direct Injection | |
| Number of doors | 5 | |
| Number of seats CarCheck.co.uk | 5 page : | 11/11 |

Number of axles 2

Engine number D4HBGU493660