



Mercedes-Benz

WK60VGP

report date: 2024-03-29

General information

Make	MERCEDES
Model	VITO 111 CDI LONG P/V
Colour	Black
Year of manufacture	2010
Gearbox	6 speed Manual

Engine & fuel consumption

Power	116 BHP
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-08
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-26
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	57
Total items failed	9

MOT #172023-09-22 06:48

MOT test number777638799597

Result✓ Passed

Next expiry date2024-09-26

- Advice** Pas pipes corroded
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Integral body structure is corroded but structural rigidity is not significantly reduced underside (6.1.1 (c) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Oil leak, but not excessive diff (8.4.1 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #162022-09-27 15:18

MOT test number174864230395

Result✓ Passed

- Advice** Integral body structure is corroded but structural rigidity is not significantly reduced underside of the vehicle (6.1.1 (c) (i))
- Advice** Oil leak, but not excessive from engine and rear diff (8.4.1 (a) (i))
- Advice** Power steering pipe/hose slightly corroded (2.1.5 (g) (i))

**MOT #15**

2022-09-22 08:54

MOT test number

707161715184

Result

✗ Failed

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Integral body structure is corroded but structural rigidity is not significantly reduced underside of the vehicle (6.1.1 (c) (i))**Advice** Power steering pipe/hose slightly corroded (2.1.5 (g) (i))**Advice** Oil leak, but not excessive from engine and rear diff (8.4.1 (a) (i))**Fail** Nearside Rear Coil spring fractured or broken also corroded (5.3.1 (b) (i))**MOT #14**

2021-09-22 12:53

MOT test number

271406603342

Result

✓ Passed

MOT #13

2020-12-16 16:28

MOT test number

435075355207

Result

✓ Passed

MOT #12

2019-12-18 09:25

MOT test number

297549142627

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Fluid leak, but not excessive diff (8.4.1 (a) (i))**Advice** Offside Rear Brake pad(s) wearing thin on limit (1.1.13 (a) (ii))**Advice** Front Direction indicator slightly discoloured both (4.4.3 (a))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Passenger seat(s) missing at time of test

**MOT #11**

2019-12-18 09:24

MOT test number

434599868024

Result**✗ Failed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Fluid leak, but not excessive diff (8.4.1 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Passenger seat(s) missing at time of test**Advice** Offside Rear Brake pad(s) wearing thin on limit (1.1.13 (a) (ii))**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Front Direction indicator slightly discoloured both (4.4.3 (a))**MOT #10**

2018-12-22 12:14

MOT test number

379864560132

Result**✓ Passed****Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear seats removed**Minor** Windscreen damaged but not adversely affecting driver's view small stone chip (3.2 (a) (i))**MOT #9**

2018-12-22 12:14

MOT test number

389511980211

Result**✗ Failed****Advice** Rear seats removed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))**Minor** Windscreen damaged but not adversely affecting driver's view small stone chip (3.2 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))



MOT #8

2017-12-19 14:00

MOT test number

588929284085

Result

✓ Passed

- Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice

Exhaust tail pipe corroded
- Advice

Exhaust has a minor leak of exhaust gases tail pipe (7.1.2)
- Advice

Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice

Rear seats removed
- Advice

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #7** 2017-12-19 09:51**MOT test number** 187196467241**Result** ✗ Failed

- Advice** Exhaust has a minor leak of exhaust gases tail pipe (7.1.2)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Rear Brake pad(s) less than 1.5 mm thick both (3.5.1g)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Exhaust tail pipe corroded
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear seats removed
- Fail** Offside Rear brake disc in such a condition that it is seriously weakened metal to metal with pads (3.5.1i)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT #6 2016-12-20 15:07**MOT test number** 149851999731**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2015-12-21 15:42**MOT test number** 646987744485**Result** ✓ Passed

**MOT #4** 2015-12-21 10:04**MOT test number** 228290021482**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #3** 2014-11-03 11:23**MOT test number** 406897304452**Result** ✓ Passed**Notice** Rear differential oil seal leaking**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-10-25 15:47**MOT test number** 699448393256**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Poss tracking fault**MOT #1** 2013-10-25 14:19**MOT test number** 278028293234**Result** ✗ Failed**Notice** Poss tracking fault**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
26 September 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	26 September 2024
Full MOT history	See MOT history



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-10-28
Last registration	2023-09-22
Complete history	See info



Registration #1	2010-10-28	12 mi
Registration #2	2013-10-25	40.493 mi
Registration #3	2013-10-25	40.496 mi
Registration #4	2014-11-03	57.524 mi
Registration #5	2015-12-21	67.175 mi
Registration #6	2015-12-21	67.175 mi
Registration #7	2016-12-20	72.599 mi
Registration #8	2017-12-19	88.696 mi
Registration #9	2017-12-19	88.696 mi
Registration #10	2018-12-22	103.467 mi
Registration #11	2019-09-22	115.277 mi
Registration #12	2019-09-22	115.277 mi
Registration #13	2019-09-22	115.277 mi
Registration #14	2019-09-22	115.277 mi
Registration #15	2019-09-22	115.277 mi
Registration #16	2019-09-22	115.277 mi
Registration #17	2019-09-22	115.277 mi
Registration #18	2019-09-22	115.277 mi
Registration #19	2019-09-22	115.277 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6
Engine number	64698051841693