



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	GETZ CDX
Colour	Black
Year of manufacture	2008
Top speed	93 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	65 BHP
Max. torque	99 Nm at 3.200 rpm
Engine capacity	1.086 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	130 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-07-24
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-15
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	22
Total items failed	7

MOT #21	2023-11-16 11:12
MOT test number	475124887895
Result	✓ Passed
Next expiry date	2024-11-15

MOT #20	2023-11-15 18:16
MOT test number	167460785880
Result	✗ Failed
MAJOR Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))	

MOT #19	2022-07-27 10:41
MOT test number	944385255405
Result	✓ Passed

MOT #18	2022-07-25 15:30
MOT test number	922141873160
Result	✗ Failed
MAJOR Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))	
MAJOR Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))	

**MOT #17** 2021-08-12 12:03**MOT test number** 892790059151**Result** ✓ Passed**MOT #16** 2021-08-10 16:09**MOT test number** 290587446230**Result** ✗ Failed

MAJOR Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #15 2020-11-16 13:11**MOT test number** 755844701555**Result** ✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14 2020-11-16 13:11**MOT test number** 798860318376**Result** ✗ Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Pass with rectification Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #13 2019-11-14 13:03**MOT test number** 137801678869**Result** ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #12** 2019-11-14 13:03**MOT test number** 350781236430**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #11** 2018-09-14 14:09**MOT test number** 626912920283**Result** ✓ Passed**Advice** Inner Tyre worn close to legal limit/worn on edge all four (5.2.3 (e))**MOT #10** 2018-09-14 10:44**MOT test number** 872969811922**Result** ✗ Failed**MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MAJOR** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Inner Tyre worn close to legal limit/worn on edge all four (5.2.3 (e))**MAJOR** Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))**MOT #9** 2017-09-05 14:37**MOT test number** 651650826162**Result** ✓ Passed

**MOT #8** 2017-08-17 15:58**MOT test number** 927790755445**Result** ✗ Failed**Advice** Nearside front tyre outer wall has slight damage**Advice** Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt badly perished (2.5.C.1a)**Fail** Offside Front Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Offside Front Upper Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt split (2.4.G.2)**MOT #7** 2016-09-12 15:36**MOT test number** 377511126250**Result** ✓ Passed**MOT #6** 2016-09-12 07:35**MOT test number** 823168769671**Result** ✗ Failed**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #5** 2015-09-24 08:36**MOT test number** 218379329077**Result** ✓ Passed**Advice** Both front outer c/v gaiters are perishing and deeply cracked.**MOT #4** 2014-09-18 14:18**MOT test number** 396951864412**Result** ✓ Passed



MOT #3	2013-09-05 12:04
MOT test number	649448743270
Result	✓ Passed
MOT #2	2012-09-14 14:54
MOT test number	716898252291
Result	✓ Passed
MOT #1	2011-09-30 15:07
MOT test number	735953271220
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
15 November 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	15 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EK58ECZ
Plate since	2019-03-29
Current registration	EK58ECZ
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2008-09-30
Last registration	2023-11-16
Complete history	See info



Registration #1	2008-09-30	12 mi
Registration #2	2011-09-30	25.384 mi
Registration #3	2012-09-14	36.033 mi
Registration #4	2013-09-05	51.072 mi
Registration #5	2014-09-18	60.060 mi
Registration #6	2015-09-24	71.881 mi
Registration #7	2016-09-12	81.150 mi
Registration #8	2016-09-12	81.150 mi
Registration #9	2017-08-17	88.034 mi
Registration #10	2017-09-05	88.048 mi
Registration #11	2018-09-14	93.058 mi
Registration #12	2018-09-14	93.061 mi
Registration #13	2019-09-14	93.061 mi
Registration #14	2019-09-14	93.061 mi
Registration #15	2019-09-14	93.061 mi
Registration #16	2019-09-14	93.061 mi
Registration #17	2019-09-14	93.061 mi
Registration #18	2019-09-14	93.061 mi
Registration #19	2019-09-14	93.061 mi
Registration #20	2019-09-14	93.061 mi
Registration #21	2019-09-14	93.061 mi
Registration #22	2019-09-14	93.061 mi
Registration #23	2019-09-14	93.061 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3825 mm
Wheel base	2455 mm
Kerb weight	998 kg
Max. allowed weight	1440 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4HG8476034