



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D DRIVE S
Colour	Silver
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-08-24
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-27
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	37
Total items failed	7

MOT #19	2023-09-28 14:35
MOT test number	644197633719
Result	✓ Passed
Next expiry date	2024-09-27
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge INNER EDGE (5.2.3 (e))
Advice	Suspension arm pin or bush worn but not resulting in excessive movement REAR SUSPENSION, LOWER FRONT-MOST LATERAL LINK ARMS BOT SIDES (5.3.4 (a) (i))
Advice	FOUR WHEEL ALIGNMENT REQUIRED
Advice	Nearside Track rod end ball joint has slight play INNER AND OUTER (2.1.3 (b) (i))

**MOT #18**

2023-09-27 09:16

MOT test number

357329247365

Result**✗ Failed**

MAJOR Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Suspension arm pin or bush worn but not resulting in excessive movement REAR SUSPENSION, LOWER FRONT-MOST LATERAL LINK ARMS BOT SIDES (5.3.4 (a) (i))

DANGEROUS Nearside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii))

MAJOR Suspension arm pin or bush excessively worn BOTH FRONT ARM REAR-MOST BUSHES (5.3.4 (a) (i))

DANGEROUS Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Track rod end ball joint has slight play INNER AND OUTER (2.1.3 (b) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge INNER EDGE (5.2.3 (e))

Advice FOUR WHEEL ALIGNMENT REQUIRED

MOT #17

2022-09-28 08:47

MOT test number

512335165274

Result**✓ Passed**

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge bald inner (5.2.3 (e))

Advice Suspension arm pin or bush worn but not resulting in excessive movement Both front arm rear bushes (5.3.4 (a) (i))

**MOT #16**

2022-09-28 08:47

MOT test number

281763693717

Result**✗ Failed****Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge bald inner (5.2.3 (e))**Advice** Suspension arm pin or bush worn but not resulting in excessive movement Both front arm rear bushes (5.3.4 (a) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))**MOT #15**

2021-09-15 14:59

MOT test number

627492968241

Result**✓ Passed****MOT #14**

2021-09-13 16:33

MOT test number

800121086800

Result**✗ Failed****MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 205/55/16 (5.2.3 (d) (i))**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**MOT #13**

2020-09-16 14:55

MOT test number

392676797077

Result**✓ Passed****Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Undertrays fitted

**MOT #12**

2020-09-16 09:51

MOT test number

725984565155

Result**✗ Failed****Advice** Undertrays fitted**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #11**

2019-09-13 09:36

MOT test number

324669590640

Result**✓ Passed****Advice** Undertrays fitted**MOT #10**

2018-09-07 09:59

MOT test number

596741000680

Result**✓ Passed****Advice** Under tray fitted**MOT #9**

2017-09-26 14:09

MOT test number

769953039795

Result**✓ Passed****MOT #8**

2017-09-26 12:06

MOT test number

451771089581

Result**✗ Failed****Fail** Offside Rear Anti-roll bar linkage missing (2.4.G.1)

**MOT #7** 2016-09-26 11:07**MOT test number** 812895433951**Result** ✓ Passed**MOT #6** 2016-09-26 10:46**MOT test number** 960187171345**Result** ✗ Failed**Fail** Offside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**MOT #5** 2015-09-23 10:56**MOT test number** 585196864527**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2014-09-25 14:22**MOT test number** 977368664264**Result** ✓ Passed**MOT #3** 2013-09-06 14:47**MOT test number** 567129643232**Result** ✓ Passed**MOT #2** 2012-09-12 12:33**MOT test number** 226596852285**Result** ✓ Passed**Notice** Front tyres worn on inner edges



MOT #1	2012-09-12 11:38
MOT test number	749076452248
Result	✗ Failed
<div><div>Notice</div>Front tyres worn on inner edges</div> <div><div>Fail</div>Offside Rear Registration plate lamp not working (1.1.C.1d)</div> <div><div>Fail</div>Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
27 September 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	27 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history


Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-28
Current registration	
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-09-22
Last registration	2023-09-28
Complete history	See info



Registration #1	2009-09-22	26 mi
Registration #2	2012-09-12	36.007 mi
Registration #3	2012-09-12	36.007 mi
Registration #4	2013-09-06	48.471 mi
Registration #5	2014-09-25	55.396 mi
Registration #6	2015-09-23	60.361 mi
Registration #7	2016-09-26	65.105 mi
Registration #8	2016-09-26	65.105 mi
Registration #9	2017-09-26	70.582 mi
Registration #10	2017-09-26	70.582 mi
Registration #11	2018-09-07	76.616 mi
Registration #12	2019-09-28	81.557 mi
Registration #13	2020-09-28	86.500 mi
Registration #14	2021-09-28	91.443 mi
Registration #15	2022-09-28	96.386 mi
Registration #16	2023-09-28	101.329 mi
Registration #17	2023-09-28	101.329 mi
Registration #18	2023-09-28	101.329 mi
Registration #19	2023-09-28	101.329 mi
Registration #20	2023-09-28	101.329 mi
Registration #21	2023-09-28	101.329 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1408 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	884000
---------------	--------