





report date: 2024-03-29

General information

Make	NISSAN
Model	PATHFINDER DCI TEKNA
Colour	Silver
Year of manufacture	2011
Top speed	115 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	450 Nm at 2.000 rpm
Engine capacity	2.488 сс
Cylinders	4
Fuel type	Diesel
Consumption city	23.5 mpg
Consumption extra urban	38.7 mpg
Consumption combined	31.4 mpg
CO2 emission	238 g/km
CO2 label	L



CarCheck.co.uk page 1/13



report date: 2024-03-29


Internet history

Entry 1

Date 2022-02-03

Pictures 3

Listing price <u>View report</u>







source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2024-08-16
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	13
Total items failed	8

MOT #14	2023-08-17 16:08
MOT test number	835492534782
Result	✓ Passed
Next expiry date	2024-08-16
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #13	2023-08-17 09:52
MOT test number	312581642734
Result	× Failed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #12	2022-08-03 09:44
MOT test number	355788094285
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #11 2022-08-02 15:26

MOT test number 729922995842

Result X Failed

Fail Nearside Front Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))

Fail Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))

MOT #10 2021-11-09 18:29

MOT test number 996773757583

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Prop shaft joint worn, but not excessively (6.1.7 (c) (i))

MOT #9 2020-11-02 16:28

MOT test number 815791321825

Result ✓ Passed

MOT #8 2020-10-30 11:41

MOT test number 772833854737

Result X Failed

Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Fail Offside Rear Service brake excessively binding (1.2.1 (f))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #7

MOT test number

648551274530

Result

Advice Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))

Advice Offside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))

MOT #6

MOT test number

116564036756

Result

Advice

Offside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))

Advice

Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))

Fail

Nearside Side repeater light intensity significantly reduced (4.4.3 (a))

MOT test number

Result

Advice

Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice

Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #4	2017-10-23 13:06
MOT test number	572761860541
Result	✓ Passed
MOT #3	2016-10-19 11:51
MOT test number	761083763834
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #2	2015-10-26 17:00
MOT test number	956365318619
Result	✓ Passed
MOT #1	2014-10-29 16:08
	2011102310.00
MOT test number	948002704325

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	16 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

_	
Owner	history
OWITCE	ilistoi y

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
have: Check it in the premium report and see an owner registrations. Download the full r	eport <u>nere</u> .

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	UK UK
Rinto circo	UK C
Current registration	NE NE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-10-31
Last registration	2023-08-17
Complete history	See info



Registration #1	2011-10-31	14 mi
Registration #2	2014-10-29	22.646 mi
Registration #3	2015-10-26	33.043 mi
Registration #4	2016-10-19	39.919 mi
Registration #5	2017-10-23	46.292 mi
Registration #6	2018-10-11	62.052 mi
Registration #7	2019-10-21	73.636 mi
Registration #8	2019-10-30	74.054 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777-00

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1848 mm
Height	1785 mm
Length	4813 mm
Wheel base	2853 mm
Kerb weight	2140 kg
Max. allowed weight	2880 kg

Additional information

Fuel tank capacity	80
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/13

Number of axles2Engine number04319B