





report date: 2024-03-29

#### General information

Make	AUDI
Model	A4 TFSI QUATTRO S LINE SPECIAL EDITION
Colour	Silver
Year of manufacture	2010
Top speed	153 mph
Gearbox	7 speed automatic

## Engine & fuel consumption

Power	211 BHP
Max. torque	350 Nm at 4.200 rpm
Engine capacity	1.984 сс
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	38.2 mpg
Consumption combined	44.8 mpg
CO2 emission	174 g/km
CO2 label	Н



CarCheck.co.uk page 1/14



### Internet history

#### Entry 1

Date	2021-07-27
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-08-26
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	23
Total items failed	8

08-08 13:32
188868111
✓ Passed
2024-08-26

MOT #14	2022-08-25 13:48
MOT test number	356121303318
Result	<b>✓</b> Passed
MOT #13	2021-08-27 09:35
MOT test number	931041313201
Result	✓ Passed

CarCheck.co.uk page 3/14



MOT #12 2021-08-20 13:33

**MOT test number** 443910397765

**Result** X Failed

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #11** 2021-03-19 15:54

MOT test number 373343298648

Result \rightarrow Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Back bush (5.3.4 (a) (i))

**Advice** Brake disc worn, pitted or scored, but not seriously weakened Both rears (1.1.14 (a) (ii))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Back bush (5.3.4 (a) (i))

Advice Rear Shock absorbers light misting of oil or has limited damping effect Both (5.3.2 (b))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/14



**MOT #10** 2021-03-19 11:48

**MOT test number** 770617007207

**Result** X Failed

Advice Brake disc worn, pitted or scored, but not seriously weakened Both rears (1.1.14 (a) (ii))

Fail Offside Obligatory indirect vision device does not provide a view to the rear (3.3 (c))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Back bush (5.3.4 (a) (i))

**Advice** Rear Shock absorbers light misting of oil or has limited damping effect Both (5.3.2 (b))

**Advice** Nearside Rear Nail in tyre

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Front Side repeater not working (4.4.1 (a) (ii))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Back bush (5.3.4 (a) (i))

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #9 2020-03-20 12:42

**MOT test number** 137696117928

**Result** 
✓ Passed

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #8 2019-03-22 12:58

**MOT test number** 222791866595

**Result** ✓ Passed

MOT #7 2018-03-22 15:18

**MOT test number** 615827155505

**Result** ✓ Passed

CarCheck.co.uk page 5/14



MOT #6 2017-03-23 14:56 **MOT test number** 282756822684 Result ✓ Passed MOT #5 2016-03-15 15:02 **MOT** test number 806065457290 Result ✓ Passed MOT #4 2015-03-16 14:50 **MOT test number** 108235175446 Result ✓ Passed MOT #3 2014-03-24 09:28 145983684033 **MOT test number** Result ✓ Passed MOT #2 2013-06-20 15:30 **MOT test number** 879601073184 Result ✓ Passed **Notice** Under-trays fitted obscuring some underside components **Notice** Engine covers fitted obscuring some components in the engine bay

CarCheck.co.uk page 6/14



MOT #1 2013-06-19 12:57 **MOT test number** 875640873145 Result × Failed Notice Under-trays fitted obscuring some underside components Notice Both rear tyres cracking Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Notice Engine covers fitted obscuring some components in the engine bay Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail

CarCheck.co.uk page 7/14



## Tax & MOT check

Tax expired: 1 April 2024





Tax status	Expired at 1 April 2024
Days left	29 days too late
MOT expiry date	26 August 2024
Full MOT history	See MOT history

Expires: 26 August 2024

#### Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 8/14



#### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



#### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



_		
Owne	 	
	ΙСΤ	nrv
	 IJL	

For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report J	
manage of the same	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	NK AIN
Plate since	
Current registration	UK NAME OF THE PROPERTY OF THE
Plate since	
	More info >

CarCheck.co.uk page 11/14



#### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



## Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-06-26
Last registration	2023-08-08
Complete history	See info



Registration #1	2010-06-26	24 mi
Registration #2	2013-06-19	23.185 mi
Registration #3	2013-06-20	23.188 mi
Registration #4	2014-03-24	29.178 mi
Registration #5	2015-03-16	34.304 mi
Registration #6	2016-03-15	39.550 mi
Registration #7	2017-03-23	44.389 mi
Registration #8	2018-03-22	49.710 mi
Registration #9	2019-03-22	53.292 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		

More info >

CarCheck.co.uk page 13/14



### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Adult	93%
Children	84%
Pedestrian	39%
Safety systems	71%
Overall rating	78%
Video	see crash video



## Dimensions & weight

Width	1826 mm
Height	1427 mm
Length	4703 mm
Wheel base	2808 mm
Kerb weight	1525 kg
Max. allowed weight	2115 kg

# Additional information

Fuel tank capacity	64 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 page	14/14

Number of axles 2

Engine number CDN 129336