





report date: 2024-03-28

General information

Make	CITROEN
Model	C4 GRAND BLUEHDI EXCLUSIVE EAT6
Colour	Grey
Year of manufacture	2016
Top speed	128 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	370 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	112 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-09-02

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-10-20
MOT pass rate	50 %
MOT passed	5
Failed MOT tests	5
Total advice items	20
Total items failed	3

MOT #10	2023-09-28 14:41
MOT test number	655785548876
Result	✓ Passed
Next expiry date	2024-10-20

MOT #9		2023-09-28 07:56
MOT test number		647277108727
Result		X Failed
Advice Tyre pressure v	varning light on constantly	
Pass with rectification	Offside Rear Tyre pressure monitoring system ma	lfunctioning or obviously
inoperative pressure low rectified fore m o t (5.2.3 (h))		
Advice Front Brake pad(s) wearing thin app 70% worn monitor (1.1.13 (a) (ii))		
MAJOR Nearside Front the ingress of dirt (6.1.7 (g	Outer Drive shaft joint constant velocity boot split or (ii))	insecure, no longer prevents

MOT #8	2022-10-21 15:53
MOT test number	793677169641
Result	✓ Passed
Advice Advise o/s/r tyre 2mm tread depth	

CarCheck.co.uk page 3/12



MOT #7 2022-10-21 07:31

MOT test number 305620410258

Result X Failed

Advice Advise o/s/r tyre 2mm tread depth

Pass with rectification Offside Front Headlamp aim too low (4.1.2 (a))

MAJOR Offside Rear Registration plate lamp likely to become detached (4.7.1 (c) (ii))

Advice Advise nail in n/s/r tyre

Pass with rectification Nearside Front Headlamp aim too low (4.1.2 (a))

MAJOR Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps

(4.7.2 (a))

MAJOR Nearside Front Windscreen washer not working (3.5 (a))

MOT #6 2021-09-10 12:53

MOT test number 200827567120

Result ✓ Passed

MOT #5 2021-09-09 16:04

MOT test number 751660656073

Result X Failed

DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #4 2020-11-24 16:48

MOT test number 286649075625

Result
✓ Passed

CarCheck.co.uk page 4/12



MOT #3 2020-11-18 10:34

MOT test number 989427680049

Result X Failed

MAJOR Offside Front Headlamp aim too low (4.1.2 (a))

MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MAJOR Front Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))

MAJOR Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #2 2019-05-15 14:07

MOT test number 696709728453

MOT #1 2019-05-15 09:33

MOT test number 422355800081

Result × Failed

MAJOR Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

DANGEROUS Nearside Front Anti-roll bar linkage ball joint likely to become detached (5.3.4 (a) (ii))

MAJOR Offside Front Headlamp aim too low (4.1.2 (a))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Nearside Front Headlamp aim too low (4.1.2 (a))

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	20 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-


CarCheck.co.uk page 6/12



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

owner mistery	
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	NK SIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-05-19
Last registration	2023-09-28
Complete history	See info



Registration #1	2016-05-19	20 mi
Registration #2	2019-05-15	45.500 mi
Registration #3	2019-05-15	45.500 mi
Registration #4	2020-11-18	61.442 mi
Registration #5	2020-11-24	61.443 mi
Registration #6		71.777 es
Registration #7		11.777 mi
Registration #8		11.777 es
Registration #9		11.177 mi
Registration #10		11.777 ea
Registration #11		11.177 ms
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1826 mm
Height	1656 mm
Length	4597 mm
Wheel base	2840 mm
Kerb weight	1476 kg
Max. allowed weight	2280 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	DYZP4035484

CarCheck.co.uk page 12/12