





report date: 2024-03-30

#### General information

Make	MINI
Model	MINI ONE
Colour	Red
Year of manufacture	2012
Top speed	116 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/12



MOT history

MOT expiry date	2024-11-15
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	18
Total items failed	1

MOT #13	2023-11-15 11:38
MOT test number	302971263324
Result	<b>✓</b> Passed
Next expiry date	2024-11-15

MOT #12		2023-11-13 09:55
MOT test	number	819442036436
Result		<b>X</b> Failed
MAJOR	Offside Position lamp not working (4.2.1 (a) (ii))	
MAJOR	Nearside Position lamp not working (4.2.1 (a) (ii))	
MAJOR	Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))	

MOT #11	2022-11-16 16:22
MOT test number	737956046357
Result	✓ Passed
Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	

CarCheck.co.uk page 2/12



MOT #10

MOT test number

Result

Advice
Oil leak, but not excessive Engine (8.4.1 (a) (i))

Advice
Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

AdviceNearside Front Wheel bearing has slight play (5.1.3 (a) (i))MOT #92020-09-21 12:47MOT test number625501662380Result✓ PassedMOT #82019-10-09 13:02MOT test number104302894911Result✓ PassedAdviceOffside Rear tyre showing deterioration/cracks

CarCheck.co.uk page 3/12



**MOT #7** 2019-10-01 11:40

**MOT test number** 572851611068

Result X Failed

**DANGEROUS** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MAJOR** Offside Headlamp aim too high and too far to the right. (4.1.2 (a))

**Advice** Offside Rear tyre showing deterioration/cracks

**MAJOR** Offside Headlamp insecure outer bracket broken (4.1.1 (c))

**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MAJOR** Reversing lamp inoperative working but hidden behind bumper (4.6.1 (a))

MAJOR Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #6 2018-09-18 11:10

**MOT test number** 971731826860

Result \rightarrow Passed

MOT #5 2018-08-06 11:38

**MOT test number** 790782277528

**Result** ✓ Passed

MOT #4 2017-03-08 12:23

**MOT test number** 873611386771

Result 

Passed

CarCheck.co.uk page 4/12



MOT #3 2016-06-14 11:13

**MOT test number** 340957155601

**Result** ✓ Passed

MOT #2 2016-06-14 11:13

**MOT test number** 726177230621

Result X Failed

**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively both (8.2.2)

**MOT #1** 2015-06-15 10:27

**MOT test number** 466856965199

**Notice** Wipers split on ends

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	15 November 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>k</u>		e?
********		
***************************************		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 10/12



## Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-06-29
Last registration	2023-11-15
Complete history	See info



Registration #1	2012-06-29	21 mi
Registration #2	2015-06-15	32.640 mi
Registration #3	2016-06-14	36.870 mi
Registration #4	2016-06-14	36.870 mi
Registration #5	2017-03-08	41.775 mi
Registration #6	2018-08-06	53.204 mi
Registration #7	2018-09-18	53.214 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		D.777 es
Registration #13		91.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1530 kg

## Additional information

Fuel tank capacity	40 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles2Engine numberA024J283