





report date: 2024-03-28

General information

Make	TOYOTA
Model	AYGO VVT-I X-PLAY
Colour	Grey
Year of manufacture	2018
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	72 BHP
Max. torque	93 Nm at 4.400 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	57.6 mpg
Consumption extra urban	78.5 mpg
Consumption combined	68.9 mpg
CO2 emission	95 g/km
CO2 label	A



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

 Date
 2021-07-02

 Pictures
 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

MOT expiry date	2025-03-28
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	9
Total items failed	2

MOT #6		2024-03-21 13:43
MOT test	number	176057506645
Result		✓ Passed
Next expi	ry date	2025-03-28
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Outer Tyre slightly damaged sidewall (5.2.3 (d) (ii))	

MOT #5	2023-03-29 12:36
MOT test number	893129011352
Result	✓ Passed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	(ii))

CarCheck.co.uk page 3/11



Fail

VO18WWJ

report date: 2024-03-28

MOT #4 2023-03-24 12:04

MOT test number 997321638545

Result X Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #3 2022-03-28 14:27

MOT test number 142404060047

Result ✓ Passed

MOT #2 2022-03-28 14:27

MOT test number 608651826741

Result X Failed

Pass with rectification Nearside Front Inner Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #1 2021-03-29 08:49

MOT test number 608054039991

Result \(\sqrt{Passed} \)

Minor Central Rear Stop lamp(s) light intensity obviously reduced (4.3.3 (a) (i))

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	28 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
First licence fee (12 months)	£ 165,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



factor scincol

VO18WWJ

report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this TOYOTA had different number plates. deer of plates

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-03-29
Last registration	2024-03-21
Complete history	See info



Registration #1	2018-03-29	29 mi
Registration #2	2021-03-29	5.680 mi
Registration #3		11.777 es
Registration #4	2022-03-28	8.161 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.177 es
Registration #8		11.777 es

More info >

CarCheck.co.uk page 10/11



VO18WWJ report date: 2024-03-28

Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Adult	82%
Children	63%
Pedestrian	64%
Safety systems	57%
Overall rating	69%
Video	see crash video



Dimensions & weight

Width	1615 mm
Height	1460 mm
Length	3455 mm
Wheel base	2340 mm
Kerb weight	855 kg
Max. allowed weight	1240 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 11/11