





report date: 2024-03-29

#### General information

Make	SUZUKI
Model	VITARA SZ-T
Colour	Grey
Year of manufacture	2016
Top speed	112 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	118 BHP
Max. torque	156 Nm at 4.400 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	123 g/km
CO2 label	D



CarCheck.co.uk page 1/11



# Internet history

#### Entry 1

Date 2021-02-04

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-02-11
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	8
Total items failed	4

MOT #7	2024-02-02 10:06
MOT test number	806165472311
Result	✓ Passed
Next expiry date	2025-02-11
Advice Undertrays fitted	

MOT #6	2023-01-30 14:11
MOT test number	844615091716
Result	<b>✓</b> Passed
Advice Undercovers fitted	

MOT #5	2023-01-30 10:59
MOT test number	443172803556
Result	<b>X</b> Failed
Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4  Advice Undercovers fitted	.7.1 (b) (ii))

MOT #4	2022-01-13 16:14
MOT test number	984786330787
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



Passed

MOT #3 2022-01-13 09:45

**MOT test number** 474501188617

Result X Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm 215/55/17 (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #2 2021-02-12 12:28

MOT test number 151235296947

Result \rightarrow Passed

**Advice** N/s front tyre close to limit at time of test

Result

MOT #1 2019-06-05 10:10

**MOT test number** 627974503636

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/11



### Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	11 February 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 5/11



#### Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners have? Check it in the premium report and see all owner registrations. Download the full research		KI
***************************************		
THE PARTY OF THE P		
***************************************		
*************		
	More info	>
Plate changes		
See in this check if this SUZUKI had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



#### Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-05-27
Last registration	2024-02-02
Complete history	See info



Registration #1	2016-05-27	17 mi
Registration #2	2019-06-05	37.552 mi
Registration #3		11.777 es
Registration #4	2021-02-12	56.952 mi
Registration #5	2022-01-13	65.687 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



### Safety ratings

NCAP rating	****
Adult	89%
Children	85%
Pedestrian	76%
Safety systems	75%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	1775 mm
Height	1610 mm
Length	4175 mm
Wheel base	2500 mm
Kerb weight	1150 kg
Max. allowed weight	1730 kg

### Additional information

Fuel tank capacity	47
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	M16A-2060332

CarCheck.co.uk page 11/11