



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 CRDI SE NAV
Colour	Blue
Year of manufacture	2015
Top speed	112 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 1.800 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	145 g/km
CO2 label	F






Internet history

Entry 5

Date 2023-12-12

Pictures 8



source: g3remarketing.co.uk

Entry 4

Date 2022-11-23

Pictures 0

Listing price [View report](#)


source: carcraft.co.uk

Entry 3

Date 2022-11-20

Pictures 50

Listing price [View report](#)






source: cargurus.co.uk

Entry 2

Date 2021-09-20




Pictures 33

Listing price [View report](#)



source: yesauto.com

Entry 1	
Date	2021-09-15
Pictures	33
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-03-20
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	7
Total items failed	5

MOT #10	2024-03-21 15:08
MOT test number	278557051482
Result	✓ Passed
Next expiry date	2025-03-20

MOT #9	2024-03-21 15:08
MOT test number	400706465118
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #8	2022-11-14 15:40
MOT test number	339380263197
Result	✓ Passed

**MOT #7** 2022-11-03 13:29**MOT test number** 362664591950**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #6** 2021-09-10 12:35**MOT test number** 664439588674**Result** ✓ Passed**MOT #5** 2021-09-09 11:18**MOT test number** 353129653555**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #4** 2021-03-11 11:52**MOT test number** 492399206862**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #3	2020-02-18 11:14
MOT test number	818122137258
Result	✓ Passed
MOT #2	2019-02-22 10:14
MOT test number	738804664936
Result	✓ Passed
MOT #1	2018-02-28 11:49
MOT test number	737780843508
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
30 June 2023

✓

MOT

Expires:
20 March 2025

Tax status	Expired at 30 June 2023
Days left	303 days too late
MOT expiry date	20 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	RX15XLG
Plate since	2019-09-29
Current registration	RX15XLG
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2015-03-01
Last registration	2024-03-21
Complete history	See info



Registration #1	2015-03-01	6 mi
Registration #2	2018-02-28	24.110 mi
Registration #3	2019-02-22	29.950 mi
Registration #4	2020-02-18	36.963 mi
Registration #5	2021-03-11	45.994 mi
Registration #6	2021-09-09	46.868 mi
Registration #7	2021-09-10	46.868 mi
Registration #8	2022-03-29	55.277 mi
Registration #9	2022-03-29	55.277 mi
Registration #10	2022-03-29	55.277 mi
Registration #11	2022-03-29	55.277 mi
Registration #12	2022-03-29	55.277 mi
Registration #13	2022-03-29	55.277 mi
Registration #14	2022-03-29	55.277 mi
Registration #15	2022-03-29	55.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1679 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4HAFZ093791