



LF66FUW

report date: 2024-03-28

General information

Make	FIAT
Model	TALENTO 16V MULTIJET II
Colour	White
Year of manufacture	2016
Top speed	103 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	48.7 mpg
Consumption combined	43.5 mpg
CO2 emission	170 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-06
Pictures	18
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-21
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	17
Total items failed	1

MOT #7	2023-08-22 08:44
MOT test number	725559288575
Result	✓ Passed
Next expiry date	2024-08-21

MOT #6	2022-07-18 12:33
MOT test number	413327021546
Result	✓ Passed

MOT #5	2022-07-12 11:29
MOT test number	368245434618
Result	✗ Failed
MAJOR Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	
Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
MAJOR Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
MAJOR Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

MOT #4	2021-07-13 14:42
MOT test number	876979602059
Result	✓ Passed



MOT #3	2021-07-13 14:42
MOT test number	613330988010
Result	✗ Failed
Pass with rectification	Offside Rear Direction indicator incorrect colour (4.4.3 (a))

MOT #2	2020-09-10 13:17
MOT test number	997987800823
Result	✓ Passed
Advice	Offside Front Anti-roll bar ball joint has slight play on limit (5.3.4 (a) (i))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords outer side wall (5.2.3 (d) (i))
Advice	Offside Front Track rod end ball joint has slight play on limit (2.1.3 (b) (i))
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Front Vehicle structure is deformed but structural rigidity is not significantly reduced rear sub-frame mount poor condition (6.1.1 (a) (i))

MOT #1	2019-09-03 11:52
MOT test number	451702871117
Result	✓ Passed
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Rear Nail in tyre
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Nearside Rear Nail in tyre
Advice	Offside Front Nail in tyre



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
21 August 2024

Tax status		Valid until 1 September
Days left		125
MOT expiry date		21 August 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-11-17
Last registration	2023-08-22
Complete history	See info



Registration #1	2016-11-17	19 mi
Registration #2	2019-09-03	47.458 mi
Registration #3	2020-09-10	73.677 mi
Registration #4		
Registration #5	2021-07-13	78.566 mi
Registration #6		
Registration #7		
Registration #8		
Registration #9		

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★ ★ ★ ★ ★

Video [see crash video](#)



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	4999 mm
Kerb weight	1726 kg
Max. allowed weight	2800 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	C003366