





report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM SE BLUE DRIVE
Colour	Beige
Year of manufacture	2016
Top speed	126 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	197 BHP
Max. torque	440 Nm at 2.750 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	46.3 mpg
Consumption combined	42.2 mpg
CO2 emission	177 g/km
CO2 label	I



CarCheck.co.uk page 1/11



Internet history

E ~	+	. 1
	ILIV	

Lifety 1	
Date	2021-10-09
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-10-12
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	12
Total items failed	2

MOT #7		2023-10-12 15:41
MOT test	number	909424177193
Result		✓ Passed
Next expi	ry date	2024-10-12
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)))

MOT #6	2022-10-04 10:44
MOT test number	167371415830
Result	✓ Passed
MOT #5	2021-10-13 07:54
MOT test number	502154869783
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #4 2021-10-08 13:58

MOT test number 404484630362

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

Fail Front Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

Fail Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #3 2021-06-01 11:22

MOT test number 676866438862

Result \sqrt{Passed}

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #2 2020-06-03 09:31

MOT test number 619876255199

Result \rightarrow Passed

MOT #1 2019-04-10 10:47

MOT test number 581869567272

CarCheck.co.uk page 4/11



FA16EXF

report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	12 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



FA16EXF

report date: 2024-03-28

Owner history

Owner mistory	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-06-27
Last registration	2023-10-12
Complete history	See info



Registration #1	2016-06-27	21 mi
Registration #2	2019-04-10	22.951 mi
Registration #3	2020-06-03	29.135 mi
Registration #4	2021-06-01	33.583 mi
Registration #5	2021-10-08	36.160 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	96%
Children	89%
Pedestrian	71%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1880 mm
Height	1675 mm
Length	4700 mm
Wheel base	2700 mm
Kerb weight	2003 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	64 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 11/11

Number of axles 2

Engine number D4HBFU266408