



General information

Make	MINI
Model	MINI COOPER S
Colour	Green
Year of manufacture	2013
Top speed	141 mph
0 - 60 mph	7.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	190 BHP
Max. torque	260 Nm at 1.700 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history


Entry 3

Date	2022-11-14
Pictures	0
Listing price	View report

source: [carcraft.co.uk](#)

Entry 2

Date	2022-09-20
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-10-08
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-03
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	9
Total items failed	3

MOT #112023-06-15 13:36

MOT test number819066096575

Result✓ Passed

Next expiry date2024-07-03

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #102023-06-14 12:13

MOT test number982685220208

Result✗ Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #92022-07-04 12:09

MOT test number787400806444

Result✓ Passed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8** 2022-07-04 11:38**MOT test number** 686657119708**Result** ✗ Failed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7** 2021-10-04 15:08**MOT test number** 647167048243**Result** ✓ Passed**MOT #6** 2020-10-16 09:26**MOT test number** 157395682305**Result** ✓ Passed**MOT #5** 2020-10-16 09:26**MOT test number** 184654904324**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #4** 2019-04-17 12:10**MOT test number** 751064010813**Result** ✓ Passed**MOT #3** 2018-04-13 10:04**MOT test number** 488576487241**Result** ✓ Passed



MOT #2	2017-04-08 16:00
MOT test number	156191373280
Result	✓ Passed
MOT #1	2016-09-06 09:36
MOT test number	267729952528
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
3 July 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	3 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-09-28
Last registration	2023-06-15
Complete history	See info



Registration #1	2013-09-28	25 mi
Registration #2	2016-09-06	17.728 mi
Registration #3	2017-04-08	20.484 mi
Registration #4	2018-04-13	23.463 mi
Registration #5	2019-04-17	25.670 mi
Registration #6	2020-10-16	28.855 mi
Registration #7	2020-10-16	28.855 mi
Registration #8	2021-10-04	29.981 mi
Registration #9	2022-05-20	30.277 mi
Registration #10	2022-05-20	30.277 mi
Registration #11	2022-05-20	30.277 mi
Registration #12	2022-05-20	30.277 mi
Registration #13	2022-05-20	30.277 mi
Registration #14	2022-05-20	30.277 mi
Registration #15	2022-05-20	30.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	1892 mm
Height	1390 mm
Length	3734 mm
Wheel base	2467 mm
Kerb weight	1185 kg
Max. allowed weight	1475 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2

Engine number	A079J479
---------------	----------