





report date: 2024-03-28

General information

Make	RENAULT	
Model	TRAFIC LL29 DCI 115 PV LWB LC	
Colour	White	
Year of manufacture	2013	
Top speed	99 mph	
Gearbox	6 speed Manual	

Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	1.996 сс
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	43.5 mpg
Consumption combined	37.7 mpg
CO2 emission	198 g/km
CO2 label	J



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2022-02-03

Pictures 7

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-11-10
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	13
Total items failed	17

MOT #10	2023-11-11 09:58
MOT test number	311490950523
Result	✓ Passed
Next expiry date	2024-11-10
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Play in steering rack inner joint(s)	

MOT #9		2021-12-16 09:53
MOT test	number	416235073663
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened l	Both (1.1.14 (a) (ii))

MOT #8	2020-08-24 10:06
MOT test number	705864245531
Result	✓ Passed
Advice Front Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/13



MOT #7

MOT test number

914700185766

Result

Fail Nearside Rear Position lamp not working (4.2.1 (a) (ii))

Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #6

MOT test number

Result

Minor

Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

CarCheck.co.uk page 4/13



CE13ZKL

report date: 2024-03-28

MOT #5 2019-08-02 10:24 **MOT** test number 590516108186 Result × Failed Fail Oil leaking excessively from transmission (8.4.1 (a) (i)) Fail Central Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) **Advice** Vehicles internal headlight adjuster altered to recheck lights **Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) **Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a)) Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b)) Fail Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) Fail Offside Front Position lamp not working (4.2.1 (a) (ii)) Fail Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a)) Advice Power steering close to minimum mark (2.1.5 (b) (i)) Fail Nearside Front Electrical wiring insecure and in contact with sharp edges Abs wire (4.11 (a) (ii)) Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e)) Advice Pass with rectification Offside Front Headlamp aim too low (4.1.2 (a))

MOT #4	2018-06-21 16:07
MOT test number	921210481826
Result	✓ Passed

CarCheck.co.uk page 5/13



MOT #3

MOT test number

Result

Advice Mil light staying on

Advice Offside & nearside rear tyres worn on both edges

 MOT #2
 2016-07-08 15:40

 MOT test number
 931686440627

 Result
 ✓ Passed

MOT #1 2016-07-01 14:32 MOT test number 604442252210

Result X Failed

Fail Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Offside Front Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 6/13



Tax & MOT check



✓ MOT

Tax expired: 1 May 2023 Expires: 10 November 2024

Tax statusExpired at 1 May 2023Days left364 days too lateMOT expiry date10 November 2024Full MOT historySee MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e union matery	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
	More info >
Plate changes See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	NK NY
Flate since	
Current registration	UK NEK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-06-25
Last registration	2023-11-11
Complete history	See info



Registration #1	2013-06-25	6 mi
Registration #2	2016-07-01	92.779 mi
Registration #3	2016-07-08	92.779 mi
Registration #4	2017-07-07	114.006 mi
Registration #5	2018-06-21	134.315 mi
Registration #6	2019-08-02	151.394 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 mg

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	*****
Adult	58%
Children	79%
Pedestrian	28%
Safety systems	14%
Overall rating	51%
Video	see crash video



Dimensions & weight

Width	1904 mm
Height	1962 mm
Length	5182 mm
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	90 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	C102129

CarCheck.co.uk page 13/13