



report date: 2024-03-29

General information

Make	KIA
Model	VENGA CRDI 2
Colour	Blue
Year of manufacture	2013
Top speed	103 mph
0 - 60 mph	14.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	220 Nm at 1.750 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Diesel
Consumption city	56.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 2


Date	2021-02-01
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-21
Pictures	20
Listing price	View report



source: [yesauto.com](#)



MOT history

MOT expiry date	2025-04-06
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #10	2024-03-26 08:28
MOT test number	160564971742
Result	✓ Passed
Next expiry date	2025-04-06

MOT #9	2023-03-30 08:15
MOT test number	946890888556
Result	✓ Passed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #8	2022-03-31 14:09
MOT test number	662329180663
Result	✓ Passed
Advice	Nearside Front Play in steering rack inner joint(s)

MOT #7	2021-04-07 09:17
MOT test number	481595769903
Result	✓ Passed

**MOT #6** 2020-06-22 11:32**MOT test number** 485708611978**Result** ✓ Passed**Advice** Nearside Front play in steering rack inner joint**MOT #5** 2020-06-05 10:39**MOT test number** 180924950941**Result** ✗ Failed**Advice** Nearside Front Play in steering rack inner joint(s)**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**MOT #4** 2019-06-05 13:59**MOT test number** 711856390808**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #3** 2018-06-11 12:30**MOT test number** 237263487833**Result** ✓ Passed**Advice** O/s/f tyre worn completely down at both edges of the tread, not yet to cords**Advice** Both front wipers starting to deteriorate, but still clear the screen.**Advice** O/s/f tyre worn very close to legal limit.**MOT #2** 2017-07-07 10:43**MOT test number** 755165653553**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



MOT #1	2016-07-28 08:50
MOT test number	286585205195
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
6 April 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	6 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	GL13NXV
Plate since	2019-03-29
Current registration	GL13NXV
Plate since	2019-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-07-30
Last registration	2024-03-26
Complete history	See info



Registration #1	2013-07-30	29 mi
Registration #2	2016-07-28	13.847 mi
Registration #3	2017-07-07	17.302 mi
Registration #4	2018-06-11	33.185 mi
Registration #5	2019-06-05	50.213 mi
Registration #6	2020-06-05	59.044 mi
Registration #7	2020-06-22	59.083 mi
Registration #8	2020-06-22	59.083 mi
Registration #9	2020-06-22	59.083 mi
Registration #10	2020-06-22	59.083 mi
Registration #11	2020-06-22	59.083 mi
Registration #12	2020-06-22	59.083 mi
Registration #13	2020-06-22	59.083 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4068 mm
Wheel base	2615 mm
Kerb weight	1445 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FCDZ077858