



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM
Colour	Silver
Year of manufacture	2012
Top speed	118 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	436 Nm at 2.500 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	45.6 mpg
Consumption combined	39.2 mpg
CO2 emission	194 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-04-19
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	31
Total items failed	4

MOT #13 2024-04-20 10:57

MOT test number 272022282669

Result ✓ Passed

Next expiry date 2025-04-19

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement top bush (5.3.4 (a) (i))

MOT #12 2023-04-08 08:39

MOT test number 687898787477

Result ✓ Passed**Advice** Both front tyres low tread**Advice** Both rear tyres very low tread

MOT #11 2023-04-07 11:14

MOT test number 361669426443

Result ✗ Failed**Advice** Both front tyres low tread**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Both rear tyres very low tread

**MOT #10**

2022-03-29 16:08

MOT test number

444826805793

Result

✓ Passed

Advice Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Surface corrosion on suspension components**MOT #9**

2021-04-17 09:44

MOT test number

851295353399

Result

✓ Passed

MOT #8

2020-01-08 12:52

MOT test number

265552902820

Result

✓ Passed

Advice Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7**

2020-01-07 09:01

MOT test number

352707675624

Result**✗ Failed****Advice**

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail

Offside Front Side repeater not working (4.4.1 (a) (ii))

Advice

Rear Coil spring corroded (5.3.1 (b) (i))

Advice

Offside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice

Offside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #6

2019-01-19 10:26

MOT test number

275850379792

Result**✓ Passed****Advice**

Front wishbone bushes unbonding

MOT #5

2018-01-09 17:18

MOT test number

913708023669

Result**✓ Passed****Advice**

Front wishbone bushes unbonding

MOT #4

2017-01-04 11:30

MOT test number

890678298968

Result**✓ Passed****Advice**

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #3** 2016-01-20 10:32**MOT test number** 861763461938**Result** ✓ Passed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Front Inner Brake pad(s) wearing thin both (3.5.1g)

MOT #2 2015-01-26 15:45**MOT test number** 728286125089**Result** ✓ Passed

Advice Offside Front Side repeater has light sources not illuminating, but not more than 50% (1.4.A.2c)

MOT #1 2015-01-26 11:25**MOT test number** 818786725080**Result** ✗ Failed

Notice N/s/r tyre has screw in tread diagonally

Advice Front Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Notice Spare wheel upside down

Advice Offside Front Side repeater has light sources not illuminating, but not more than 50% (1.4.A.2c)

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
19 April 2025

Tax status	Valid until 1 September
Days left	124
MOT expiry date	19 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-01-31
Last registration	2024-04-20
Complete history	See info



Registration #1	2012-01-31	9 mi
Registration #2	2015-01-26	31.946 mi
Registration #3	2015-01-26	31.946 mi
Registration #4	2016-01-20	41.348 mi
Registration #5	2017-01-04	48.141 mi
Registration #6	2018-01-09	54.917 mi
Registration #7	2019-01-19	61.755 mi
Registration #8	2020-01-07	68.733 mi
Registration #9	2020-01-07	68.733 mi
Registration #10	2020-01-07	68.733 mi
Registration #11	2020-01-07	68.733 mi
Registration #12	2020-01-07	68.733 mi
Registration #13	2020-01-07	68.733 mi
Registration #14	2020-01-07	68.733 mi
Registration #15	2020-01-07	68.733 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1890 mm
Height	1760 mm
Length	4685 mm
Wheel base	2700 mm
Kerb weight	1946 kg
Max. allowed weight	2570 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	D4HBBU542816
---------------	--------------