





report date: 2024-03-28

General information

Make	VOLVO
Model	XC60 D5 SE AWD
Colour	Blue
Year of manufacture	2011
Top speed	127 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	212 BHP
Max. torque	440 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	41.5 mpg
CO2 emission	179 g/km
CO2 label	I



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-02-06

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-02-17
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #11	2024-02-15 18:21
MOT test number	627405836621
Result	✓ Passed
Next expiry date	2025-02-17

MOT #10	2023-02-15 12:06
MOT test number	144070864064
Result	✓ Passed

MOT #9		2023-02-15 12:06
MOT test number		482251243450
Result		X Failed
Pass with rectification	Offside Side repeater not working (4.4.1 (a) (ii))	

MOT #8	2022-02-18 12:32
MOT test number	620936405838
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #7	2020-09-01 14:30
MOT test number	214779548546
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #6 2019-09-18 15:18

MOT test number 474493328880

MOT #5 2018-08-16 12:37

MOT test number 367578388421

Result ✓ Passed

MOT #4 2017-08-02 09:33

MOT test number 186497387720

Result ✓ Passed

MOT #3 2016-08-18 12:50

MOT test number 868216055368

Result Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Undertrays and engine covers fitted.

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2015-08-05 10:41

MOT test number 159297015285

Result \(\sqrt{Passed} \)

Notice The front brake pads are wearing thin

Notice The rear brake pads are at the limit!

Notice Both front tyres are wearing slightly on the inner shoulders

CarCheck.co.uk page 4/12



Notice

AF61HFJ report date: 2024-03-28

MOT #1 2014-08-11 14:14

MOT test number 155963024205

Result

Notice Nail in nearside front tyre

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Notice Under-trays fitted obscuring some underside components

Engine covers fitted obscuring some components in the engine bay

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	17 February 2025
Full MOT history	See MOT history

Tax calculation

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e mier metery	
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
manus .	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	UK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-09-01
Last registration	2024-02-15
Complete history	See info



Registration #1	2011-09-01	11 mi
Registration #2	2014-08-11	45.283 mi
Registration #3	2015-08-05	56.862 mi
Registration #4	2016-08-18	66.355 mi
Registration #5	2017-08-02	74.071 mi
Registration #6	2018-08-16	83.386 mi
Registration #7	2019-09-18	95.616 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 mi
Registration #12		11.777 es
Registration #13		10.777 au

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1861 mm
Height	1604 mm
Length	4838 mm
Wheel base	2815 mm
Kerb weight	1883 kg
Max. allowed weight	2400 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles Carcheck.co.uk	2 page 12/12