





General information

Make	FIAT
Model	500 C S
Colour	Red
Year of manufacture	2013
Top speed	99 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP	0 < 101 A
Max. torque	102 Nm at 6.000 rpm	101 - 120 B
Engine capacity	1.242 cc	121 - 140 E
Cylinders	4	141 - 165 F
Fuel type	Petrol	166 - 185 H
Consumption city	49.6 mpg	186 - 225 J
Consumption extra urban	65.7 mpg	225+ L
Consumption combined	58.9 mpg	
CO2 emission	113 g/km	
CO2 label	С	





Internet history

Entry 1

Date Pictures 2021-12-02

12

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-10
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	4
Total items failed	12

MOT #12	2024-02-09 12:17
MOT test number	128203556419
Result	✓ Passed
Next expiry date	2025-02-10

MOT #:	11	2024-02-09 09:01
MOT te	st number	264299208840
Result		🗙 Failed
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1	(b) (ii))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Fail	Central Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #10	2023-02-11 10:38
MOT test number	780467755889
Result	✓ Passed

MOT #9		2023-02-10 16:36
MOT tes	st number	181537315488
Result		🗙 Failed
Fail	Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))	
Fail	Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))	





MOT #8	2021-09-02 11:36
MOT test	number 724819742729
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge INNER EDGE ON LIMIT (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge INNER EDGE (5.2.3 (e))

MOT #7	2020-09-17 11:26
MOT test number	461064262997
Result	✓ Passed

MOT #	6	2020-09-12 07:45
MOT te	st number	913964648783
Result		🗙 Failed
Fail (c))	Nearside Rear Parking brake lever has excessive movement indicating incorrect ad	justment (1.1.6
Fail	Offside Side repeater not working (4.4.1 (a) (ii))	
Fail	Nearside Rear Service brake effort inadequate at a wheel (1.2.1 (a) (i))	
Fail	ail Nearside Rear Brakes imbalanced across an axle (1.2.1 (b) (i))	
Fail	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail	Nearside Rear Parking brake inoperative on one side very low effort (1.4.1 (a))	

MOT #5	2019-04-25 09:34
MOT test number	147229970045
Result	✓ Passed
MOT #4	2019-04-25 09:34
MOT test number	343205662645
Result	× Failed
Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a))	





MOT #3	2018-04-25 12:32
MOT test number	817421362912
Result	✓ Passed
MOT #2	2017-04-25 09:16
MOT test number	812499319277
Result	✓ Passed
Advice Nearside Front wearing low	
Advice Offside Front wearing low	
MOT #1	2016-04-26 08:37
MOT test number	950365668994
Result	✓ Passed



Tax & MOT check

Tax due: 1 March 2025	✓ Taxed	Expires: 10 February 2025	✓ 40Т
Tax status			Valid until 1 March
Days left			307
MOT expiry date			10 February 2025
Full MOT history			See MOT history
Tax calculation			

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and a second s	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-09-01
Last registration	2024-02-09
Complete history	See info



Registration #1	2013-09-01	20 mi
Registration #2	2016-04-26	29.433 mi
Registration #3	2017-04-25	33.428 mi
Registration #4	2018-04-25	37.218 mi
Registration #5	2019-04-25	40.240 mi
Registration #6	2019-04-25	40.240 mi
Registration #7	2020-09-12	44.418 mi
Registration #8		11.117 esi
Registration #8 Registration #9		11.117 est 11.117 est
-		11.222 est 11.222 est 11.222 est
Registration #9		10.000 est 10.000 est 10.000 est 10.000 est
Registration #9 Registration #10		10.000 est 10.000 est 10.000 est 10.000 est 10.000 est
Registration #9 Registration #10 Registration #11		10.000 est 10.000 est 10.000 est 10.000 est 10.000 est 10.000 est

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1305 kg
Additional information	
Fuel tank capacity	35
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles	2
Engine number	0560529